

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

30-025-02558

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER- Salt Water Disposal		7. Unit Agreement Name
2. Name of Operator William E. Hendon, Jr. 25174		8. Farm or Lease Name State "C" 0500
3. Address of Operator 601 N. Loraine, Suite 111, Midland, TX, 79701		9. Well No. #1
4. Location of Well UNIT LETTER J 1980 FEET FROM THE East LINE AND 1980 FEET FROM THE South LINE, SECTION 16 TOWNSHIP 21 RANGE 34 NMPM.		10. Field and Pool, or Whdcat Wilson 7 Rivers West
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Obtained verbal approval from Mr. Jerry Sexton, NMOCC Hobbs, on 3/13/84 to alter previous "Intention to P&A" dated 1/9/84 (copy enclosed) and plug and permanently abandon referenced well as follows:

1. Drilled to 3418' obtaining cement returns.
2. Spot plug #1 @ 3418'. Tagged top of plug #1 @ 3260' 30 sx cmt.
3. Spotted cmt plug 2960'-2775' w/ 35 sx.
4. Set cmt retainer @ 302' and pumped 250 sx cmt. Spotted 35' cmt on top of retainer.
5. Set surface plug from 50' to ground level.
6. Removed wellhead, erect marker, and fill cellar.

Work completed March 15, 1984.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Robbie O'Donnell TITLE Production Manager DATE 3/15/84

APPROVED BY Ellen W. Seay TITLE OIL & GAS INSPECTOR DATE JUN 4 1984

CONDITIONS OF APPROVAL, IF ANY: own

RECEIVED
MAR 28 1984
OCS
HQSBS OFFICE