Form	C-1	0	•
T. OT III	O-T	v	4

## NEW MEXICO OIL CONSERVATION COMMISSION

## SANTA FE, NEW MEXICO

## **MISCELLANEOUS NOTICES**

the Commission.	th will be given the approval, with any modifications, of the plan submitted. The plan as approved should ed See additional instructions in the Rules and Reguntations by checking below:	be follow-
NOTICE OF INTENTION TO TEST CASING SHUT-OFF	NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL	
NOTICE OF INTENTION TO CHANGE PLANS	NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING	_
NOTICE OF INTENTION TO REPAIR WELL	NOTICE OF INTENTION TO PLUG WELL	X
NOTICE OF INTENTION TO DEEPEN WELL		
OIL CONSERVATION COMMISSION, Santa Fe, New Mexico.  Gentlemen:  Following is a notice of intention to do certain work a Figer Oil Company American Lease of Sec. 20 , T. 20 , R. 34	s described below at the  ada - ; t te	
Lea County.  FULL DETAILS OF F	PROPOSED PLAN OF WORK	
FOLLOW INSTRUCTIONS IN THE RUL a total depth of 4184, water wis en ld not be bailed down. It proposed fill up hole with rock about 10's 2" tubing to bottom, circulate mud we the lead wool. Tubing will then t, and a 10 sack pament plug placed	to plug this well as follows: and drive 700% of lead wool on to surface and set a 10 sack ce be raised to 3830', which is there. Subing would then be raised	op of rock. ment plug
o' and a 10 sack cement plug placed 7" casing which was comented at 20 7" casing will be knocked off and a mud to a depth of 500', where a bound placed below the fresh water zone a mud and a marker erected. Fits wi	285' with 50 sacks. all possible salvaged, hole wil ridge will be set, and 10 sock o . Hole will then be filled to s	iing up il be filled cement surface
7" casing which was comented at 25 7" casing will be knocked off and mud to a depth of 500', where a but placed below the fresh water zone	285' with 50 sacks. all possible salvaged, hole wil ridge will be set, and 10 sock o . Hole will then be filled to s	ing up  I be filled eement surface ed.
7" casing which was comented at 25 7" casing will be knocked off and a mud to a depth of 500', where a big placed below the fresh water zone mud and a marker erected. Fits will be knocked off and a marker erected. Fits will be knocked off and a marker erected.	285' with 50 sacks.  all possible salvaged, hole will ridge will be set, and 10 s ck of the set. The set of th	ing up  il be filled eement surface ed.