NEW XICO OIL CONSERVATION COM SION

Santa Fe, New Mexico

NOTICE OF INTENTION TO DRILL

Notice must be given to the Oil Conservation Commission or its proper agent and approval obtained before drifting begins. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in triplicate. One copy will be returned following approval. See additional instructions in Rules and Regulations of the Commission.

oir co				ta Fe, Nev Mex	160	April 1,	1948
Santa F	'e, New M	TION COMP Mexico.	MISSION,	T Inte		Dа	te
Gentlem							
						well to be known as_	
	Company Company	or Operator	te R-229	Leas		Vell No. 27 in	SE LEW L
of Sec.	23	_, T 2]	L, R 34	., N. M. P.M., Nes	t_Eunice	Field,	County
	1	N.	The well is	990feet (N.)	of the_8	outh line and	2970fee
			(W.) of	the East line	of Sec	. 23-21-34	
			(Give location	from section or othe	r legal subdivi	sion lines. Cross out w	rong directions.)
1						9, Assignment N	
		<u> </u>	i i				
		<u> </u>	į.				
	· · · · · · · · · · · · · · · · · · ·		1				
LOCA	AREA 65	0 ACRES L CORRECTI				as follows:Our	
Ve prop	of e	· · · · · · · · · · · · · · · · · ·	Weight Per Foot	New or Second Hand	Depth	Lauded or Cemented	Sacks Cement
8		7 *	65 20	New H	17 5 200	Cemented "	150 200
							. 200
hat the	ges in the first pro-	ductive oil	or gas sand should	re will notify you t	about37	ng or landing casing	. We estimate
\nurovo	od.		770 •	9 00			
	eds follows		ing should be	9Sincerely	yours,		
except a	s follows nough	: 7 ⁿ casi cement to	ing should be a return to so	cemented plof salt	WILSO	M OIL COMPANY	
except a	s follows nough	: 7 ⁿ casi cement to	ing should be	cemented plof salt	WILSO		~ ~
xcept a	s follows nough	: 7 ⁿ casi cement to	ing should be a return to so	p of salt by section. By	VIISO E CO		~ ~
xcept a	s follows nough	: 7 ⁿ casi cement to	ing should be a return to so	p of salt be section. By Position	VIISO Curcu P	mpany or Operator	~~
except a vith e sectio	s follows enough on or t	: 7" casi cement to wo stage	ing should be a return to so	p of salt section. By Position Send con	WIISO Control	mpany or Operator	~ ~