

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-10792
7. Unit Agreement Name
8. Farm or Lease Name State (B-10792) B-10792
9. Well No. 33
10. Field and Pool, or Wildcat Wilson (Y-72)
12. County Lin

SUNDY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Temp. Abandon
2. Name of Operator WILSON OIL COMPANY
3. Address of Operator P.O. Box 457, Artesia, New Mexico, 88210
4. Location of Well UNIT LETTER 0 990 FEET FROM THE South LINE AND 2310 FEET FROM THE East LINE, SECTION 24 TOWNSHIP 21 RANGE 34 NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3624' Gr.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well drilled to 3793' in 1949. Deepened to 4610' in 1953. Plugged back to 3759' and temp. abandon 16" casing 203' with 150sx. 7" casing 3645' with 400 sx.

Propose to plug and abandon well as follows:

50 25 sx cement plug 3759 to 3645'
25 sx cement plug at top 7" casing if shot off and pulled;
25 sx cement plug at base 16" casing;
15 sx cement plug at surface with regulation marker.
Off native mud between cement plugs.

25sx Plug Top Set

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED N. R. Lamb	TITLE Vice President	DATE 3-12-71
APPROVED BY [Signature]	TITLE SUPERVISOR DISTRICT	DATE MAY 10 1971
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

MAY 1 1971

OIL CONSERVATION COMM.
HOBBS, N. M.