

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
E 7420

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Wilson Oil Company	8. Farm or Lease Name State "H"
3. Address of Operator Box 457, Artesia, N.Mex. 88210	9. Well No. 1
4. Location of Well UNIT LETTER <u>O</u> , <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>25</u> TOWNSHIP <u>21S</u> RANGE <u>34E</u> NMPM.	10. Field and Pool, or Wildcat Wilson Y-7R
15. Elevation (Show whether DF, RT, GR, etc.) 3683 Gr.	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was completed 8-10-63. TD 4028: 4½" casing 4028' with 100 sx.
8 5/8" : casing 265' with 200 sx. Perforations 3844-3989'. Plugged back
4007'. T.A. 1745' TX est. 2000' BX 3765'.

Propose to plug well with 50 sx. across perfs. Shoot casing at 1600'
and squeeze with 35 sx. Shoot casing at 450' and squeezw with 50 sx.
15 sx. plug at surface with regulation marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M. R. Paul TITLE Vice President DATE 3/14/78

Orig. Signed by
Jerry Sexton

APPROVED BY [Signature] DATE 3/14/78