Form SG104

## NEW MEXICO STATE LAND .E SANTA FE, NEW MEXICO DEPARTMENT OF THE STATE GEOLOGIST SANTA FE

## <u>COPY</u> NOTICE OF INTENTION TO ABANDON WELL <u>C O P Y</u>

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

| · · · · · · · · · · · · · · · · · · ·         | Carlsbad, N | I. Mex., Nov. 15, 1930 |
|-----------------------------------------------|-------------|------------------------|
| Mr. R. L. Halley,                             |             |                        |
| Santa Fe, New Mexico. Carlsbad,               | N. Mex.     |                        |
| Dear Sir:                                     |             |                        |
| You are hereby notified that it is our intent |             |                        |
| No. 1 in NWSW4 of Sec. 1                      |             | , Rge. <b>33E.</b>     |
| N. M. P. M.,                                  | Oil Field,  | County.                |
| We plan to commence work on Nov. 21,          | ·····       | , 19. <b>30</b>        |

The reasons for wishing to abandon the well are as follows:

## Drilled into water.

| The present condition of the well is as follows: | Total                              | depth 3826'                                                   |
|--------------------------------------------------|------------------------------------|---------------------------------------------------------------|
| Casing left in hole -                            | 370*<br>298*<br>300*<br>40*<br>60* | of 8"<br>10"<br>12 <del>]</del> "<br>15 <del>2</del> "<br>20" |
|                                                  |                                    |                                                               |

The work which we propose to do in abandoning the well is as follows:

Plug back to 3806' and put in 200 lbs. lead wool and 25 sacks cement from 3776 to 3806\* Fill with mud-laden fluid to 1850 and cement to 1830' Fill up with mud-laden fluid. Put in common wood plug at 1840 and 5 sacks coment to 1830'.

Sincerely yours,

| Approved 19 <b>30</b>                     | Snowden & McSweeney Company                |
|-------------------------------------------|--------------------------------------------|
| Except as follows:                        | By Company or Operator.                    |
| NIN - 9 Rec'd                             | By <b>F. B. Van Horn</b> ,                 |
| JUN - 9 RECD<br>Johnston                  | Position Land Department                   |
| DUPLICATE                                 | Send communications regarding this well to |
| R. L. Halley,                             | Name F. B. Van Horn,                       |
| State Geologist or Oil and Gas Inspector. | Address Box 818, Carlsbad, N. Mexico       |