

COPIES RECEIVED		
CONTRIBUTION		
FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<p align="center"><b>SUNDRY NOTICES AND REPORTS ON WELLS</b></p> <p align="center"><small>DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p> <p>5. State Oil &amp; Gas Lease No. B-163</p>
<p>1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-</p>		<p>7. Unit Agreement Name</p>
<p>2. Name of Operator B. N. Muncy, Jr.</p>		<p>8. Farm or Lease Name Lea State</p>
<p>3. Address of Operator P.O. Box 196, Artesia, New Mexico 88210</p>		<p>9. Well No. 3</p>
<p>4. Location of Well UNIT LETTER <u>B</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>2</u> TOWNSHIP <u>21 S</u> RANGE <u>33 E</u> NMPM.</p>		<p>10. Field and Pool, or Wildcat Lynch (Y, SR)</p>
<p>15. Elevation (Show whether DF, RT, GR, etc.)</p>		<p>12. County Lea</p>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Loaded hole with 10# Brine plus 25 sacks salt water gel. Pumped 35 sacks Class C cement from 3616' to 3945' and tagged plug, shot casing @ 1900' but wouldn't pull, pumped 35 sacks Class C cement from 1850' to 1950' and tagged plug, shot casing at 1613' and pulled. Pumped 35 sacks Class C cement from 1544' to 1650' and tagged plug, 10 sacks Class C cement at surface. Set dry hole marker, filled pits & cellar and cleaned up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Operator DATE 10/26/77

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE NOV 1 1977

CONDITIONS OF APPROVAL, IF ANY: