

4. Ran 2½" OD Tubing, Rods, and Pump. Pumped 100 gals. Control Flow mixed with 40 bbls. crude oil into formation and overflushed with 400 bbls. crude oil.

HOBBS OFFICE 080
1955 SEP 5 AM 9:42

5. Recovered load oil, tested and returned well to production.