STATE OF NEW MEXICO	
ENERGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION DISTRIBUTION	Form C-103 ·
DISTRIBUTION P. O. BOX 2088 SANTA FE SANTA FE, NEW MEXICO 87501	Revised 10-1-78
FILE 0+2 Hobbs OCD U.S.G.S. 1 Warrior California OFERATOR 1 File	Sa. Indicate Type of Lease State Y Fee 5, State Cil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO BALL ON TO DEEPEN ON PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
I. DIL SAB DOTHER-	7, Unit Agreement Name
2, Name of Operator	8. Farm or Lease Name
Warrior, Inc.,	Lea 407 State
3. Address of Operator	9. Well No.
% Unique Engineering, Inc. P. O. Box 5315, Hobbs, NM 88241	4
4, Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER E, 1904 FEET FROM THE North LINE AND 330 FEET FROM	Eumont Yates 7-R Queen
THE West LINE, SECTION 2 TOWNBHIP 21S RANGE 35E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK X TEMPOBARILY ABANDON COMMENCE DR:LLING OPNS. COMMENCE DR:LLING OPNS. C PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB	ALTERING CASING
OTHER	L)
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed works SEE RULE 1903.	
RU pulling unit 11/8/83. Pull rods & pump. Swabbed tubing dry. Insta tubing. Set CIBP @ 3780', dumped 2 sacks of cement on top. Perforated 3680, 83, 86, 89, 92, 3703, 06.	

Picked up 2½" tubing and 5½" packer. Set packer @ 3606'. Acidized with 2400 gallons 15% acid with additives. Frac down tubing with 30,000 gallons gelled water and 58,000# sand. Return well to pumping. Testing continues 11/15/83.

•

•

1

i.



.

•

