O. OF COPIES RECEIVED				Form C-103 Supersedes Old
DISTRIBUTION				C-102 and C-103
TA FE	NEW MEXIC	CO OIL CONSERVAT	TON COMMISSION	Effective 1-1-65
.E				
s.G.S.				5a. Indicate Type of Lease
ND OFFICE			•	State Fee
ERATOR				5. State Oil & Gas Lease No.
				- Inninimin
(DO HOT USE THIS FORM THE	NDRY NOTICES AND REPROPOSITION FOR FEMALE OR TO THE	EPORTS ON WELL	S A DIFFERENT RESERVOIR, DALS.)	
x		,		7. Unit Agreement Nume
OIL GAS WELL WELL	OTHER-			~
Skelly Oil Company				8, Farm or Lease Name
· · · · · · · · · · · · · · · · · · ·				Mexico "W"
Preside (Bensol351, Mi	dland Towns 70701	. <u></u>		9. Weli No.
	demind, leads /9/01	•		2
cation of Well 7	2970	0		10. Field and Pool, or Wildoot
	47/U	South	330	Eumont
UNIT LETTER EAST	FEET FROM 18		ANDFE	ET FROM THITTING
	2	218	35E	
THE LINE, S	ECTION TOWN	ISHIP	RANGE	- nwow. {{\}}\}\}\}\
mannin	TTTTTT Elmotion	Show whether DE RT	'. GR. etc.)	12, County
	15, Elevation	(Show whether DF, RT 3573	ĎF	Lea
	7117111			
	eck Appropriate Box To F INTENTION TO:	o Indicate Nature		OF Other Data QUENT REPORT OF:
				
ORM REMEDIAL WORK	PLUG AN	D ADANDON REMEI	DIAL WORK	ALTERING CASING
PORARILY ABANDON			ENCE DRILLING OPHS.	PLUG AND ABANDONMENT
OR ALTER CASING	CHANGE	PLANS CASIN	IG TEST AND CEMENT JOB	reat Seven Rivers zone.
		i i		~~ VCVCH ALVEEN ZAMA.
		01	HER	2000,
)THER		• • • • • • • • • • • • • • • • • • •	HER	20101
Describe Proposed or Complete work) SEE RULE 1103.		all pertinent details, an	d give pertinent dates, i	including estimated date of starting any proposed
Describe Proposed of Complete work) SEE RULE 1703.) Moved in workove) Fracture treated 13,500 gallons 5 sand. Flushed w) Set 126 joints () Returned well to	er rig Märch 25, 19 i perfs. 3866-3897 5% acid, 836,000 So with 1000 gallons if (3818') 2-3/8" On •	oll pertinent details, and property of the pertinent details, and p	ods and tubing. llons foam pad, ,800# 100 mesh	including estimated date of starting any proposed
Describe Proposed of Complete work) SEE RULE 1703.) Moved in workove) Fracture treated 13,500 gallons 5 sand. Flushed w) Set 126 joints () Returned well to	er rig March 25, 19 l perfs. 3866-3897 5% acid, 836,000 So with 1000 gallons in (3818') 2-3/8" OD to producing status	oll pertinent details, and property of the pertinent details, and p	ods and tubing. llons foam pad, ,800# 100 mesh	45,000# gelled foam frac, sand and 57,500# 20/40
Describe Proposed or Complete work) see RULE 1103.) Moved in workove) Fracture treated 13,500 gallons 5 sand. Flushed w) Set 126 joints () Returned well to	er rig March 25, 19 l perfs. 3866-3897 5% acid, 836,000 So with 1000 gallons in (3818') 2-3/8" OD to producing status	oll pertinent details, and property of the pertinent details, and p	ods and tubing. llons foam pad, ,800# 100 mesh	45,000# gelled foam frac, sand and 57,500# 20/40
Describe Proposed or Complete work) SEE RULE 1103.) Moved in workove) Fracture treated 13,500 gallons 5 sand. Flushed w) Set 126 joints () Returned well to	er rig March 25, 19 l perfs. 3866-3897 5% acid, 836,000 So with 1000 gallons in (3818') 2-3/8" OD to producing status	oll pertinent details, and property of the pertinent details, and p	ods and tubing. llons foam pad, ,800# 100 mesh	45,000# gelled foam frac, sand and 57,500# 20/40
Describe Proposed of Complete work) SEE RULE 1703.) Moved in workove) Fracture treated 13,500 gallons 5 sand. Flushed w) Set 126 joints () Returned well to	er rig March 25, 19 l perfs. 3866-3897 5% acid, 836,000 So with 1000 gallons in (3818') 2-3/8" OD to producing status	oll pertinent details, and property of the pertinent details, and p	ods and tubing. llons foam pad, ,800# 100 mesh	45,000# gelled foam frac, sand and 57,500# 20/40
Describe Proposed of Complete work) SEE RULE 1703.	er rig March 25, 19 l perfs. 3866-3897 5% acid, 836,000 So with 1000 gallons in (3818') 2-3/8" OD to producing status	oll pertinent details, and property of the pertinent details, and p	ods and tubing. llons foam pad, ,800# 100 mesh	45,000# gelled foam frac, sand and 57,500# 20/40
Describe Proposed of Complete work) SEE RULE 1703.) Moved in workove) Fracture treated 13,500 gallons 5 sand. Flushed w) Set 126 joints () Returned well to	er rig March 25, 19 l perfs. 3866-3897 5% acid, 836,000 So with 1000 gallons in (3818') 2-3/8" OD to producing status	oll pertinent details, and property of the pertinent details, and p	ods and tubing. llons foam pad, ,800# 100 mesh	45,000# gelled foam frac, sand and 57,500# 20/40
Describe Proposed of Complete work) SEE RULE 1703.) Moved in workove) Fracture treated 13,500 gallons 5 sand. Flushed w) Set 126 joints () Returned well to	er rig March 25, 19 l perfs. 3866-3897 5% acid, 836,000 So with 1000 gallons in (3818') 2-3/8" OD to producing status	oll pertinent details, and property of the pertinent details, and p	ods and tubing. llons foam pad, ,800# 100 mesh	45,000# gelled foam frac, sand and 57,500# 20/40
Describe Proposed of Complete work) SEE RULE 1703.) Moved in workove) Fracture treated 13,500 gallons 5 sand. Flushed w) Set 126 joints () Returned well to	er rig March 25, 19 l perfs. 3866-3897 5% acid, 836,000 So with 1000 gallons in (3818') 2-3/8" OD to producing status	oll pertinent details, and property of the pertinent details, and p	ods and tubing. llons foam pad, ,800# 100 mesh	45,000# gelled foam frac, sand and 57,500# 20/40
Describe Proposed or Complete work) SEE RULE 1103.) Moved in workove) Fracture treated 13,500 gallons 5 sand. Flushed w) Set 126 joints () Returned well to for 5 bbls. oil,	er rig March 25, 19 i perfs. 3866-3897 i acid, 836,000 So oth 1000 gallons i (3818') 2-3/8" OD t producing status and 6 bbls. water	oll pertinent details, and office of with 1335 gal of the per day.	ods and tubing. llons foam pad, ,800# 100 mesh , pumping Seve	45,000# gelled foam frac, sand and 57,500# 20/40
work) SEE RULE 1703. 1) Moved in workove 2) Fracture treated 13,500 gallons 5 sand. Flushed w 3) Set 126 joints (4) Returned well to	er rig March 25, 19 i perfs. 3866-3897 iZ acid, 836,000 So oth 1000 gallons if (3818') 2-3/8" OD to producing status and 6 bbls. water	old pertinent details, and office of the best of my k	ods and tubing. llons foam pad, 800# 100 mesh , pumping Seve	45,000# gelled foam frac, sand and 57,500# 20/40 n Rivers perfs. 3866-3897'
Describe Proposed or Complete work) SEE RULE 1103. Describe Proposed or Complete work) SEE RULE 1103. Practure treated 13,500 gallons 5 sand. Flushed with Set 126 joints (Complete William Set 126	er rig March 25, 19 i perfs. 3866-3897 iZ acid, 836,000 So otth 1000 gallons if (3818') 2-3/8" OD to o producing status and 6 bbls. water D. R. Crow	oll pertinent details, and office of the best of my k	ods and tubing. llons foam pad, ,800# 100 mesh , pumping Seve	45,000# gelled foam frac, sand and 57,500# 20/40 n Rivers perfs. 3866-3897'
Describe Proposed or Complete work) SEE RULE 1103. 1) Moved in workove 2) Fracture treated 13,500 gallons 5 sand. Flushed w 3) Set 126 joints (4) Returned well to for 5 bbls. oil,	perfs. 3866-3897 of acid, 836,000 Sofith 1000 gallons in (3818') 2-3/8" OD to producing status and 6 bbls. water D. R. Crow	old pertinent details, and office of the best of my k	ods and tubing. llons foam pad, 800# 100 mesh , pumping Seve	45,000# gelled foam frac, sand and 57,500# 20/40
Describe Proposed or Complete work) SEE RULE 1103. Describe Proposed or Complete work) SEE RULE 1103. Practure treated 13,500 gallons 5 sand. Flushed with Set 126 joints () Returned well to for 5 bbls. oil, Thereby certify that the information (Signed D. P. Complete work) Signed D. P. Complete work of the proposed of Complete work) See RULE 1103. Thereby certify that the information (Signed D. P. Complete work) See RULE 1103.	er rig March 25, 19 i perfs. 3866-3897 iZ acid, 836,000 So rith 1000 gallons if (3818') 2-3/8" OD to producing status and 6 bbls. water D. R. Crow	oll pertinent details, and office of the best of my k	ods and tubing. llons foam pad, 800# 100 mesh , pumping Seve	45,000# gelled foam frac, sand and 57,500# 20/40 n Rivers perfs. 3866-3897'
Describe Proposed or Complete work) SEE RULE 1103. Describe Proposed or Complete work) SEE RULE 1103. Practure treated 13,500 gallons 5 sand. Flushed w Set 126 joints (Returned well to for 5 bbls. oil, Thereby certify that the information (Signed D. P. Complete work)	perfs. 3866-3897 of acid, 836,000 Sofith 1000 gallons in (3818') 2-3/8" OD to producing status and 6 bbls. water D. R. Crow	oll pertinent details, and office of the best of my k	ods and tubing. llons foam pad, 800# 100 mesh , pumping Seve	45,000# gelled foam frac, sand and 57,500# 20/40 n Rivers perfs. 3866-3897'

CONDITIONS OF APPROVAL, IF ANY: