

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
<b>State B-1399</b>

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> <b>T.A. ( Oil Well)</b>	7. Unit Agreement Name
2. Name of Operator <b>Wilson Oil Company</b>	8. Farm or Lease Name <b>Shell-Stat</b>
3. Address of Operator <b>Box 4575 Artesia, New Mexico 88210</b>	9. Well No. <b>9</b>
4. Location of Well UNIT LETTER <b>E</b> <b>2310</b> <b>North</b> <b>990</b> FEET FROM THE LINE AND FEET FROM <b>West</b> <b>7</b> <b>21S</b> <b>35E</b> THE LINE, SECTION TOWNSHIP RANGE NMPM.	10. Field and Pool, or Wildcat <b>Wilson-Y-7Rivers</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3668' Gr.</b>	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The subject well was drilled to 3759' in 1941 and deepened to 5007' in 1954'. well was then recompleted thru perfs in 5 1/2" liner at 3725-40'. Well was temp. abandon in 1969.

Propose to plug and abandon as follows.

- 25 sx plug across perfs. 3725-40'
- 25 sx plug at top salt
- 25 sx plug at top of 42 casing if knocked off and pulled.
- 25 sx cement plug at base of surface casing.
- 15 sx cement plug at surface with regulation marker.
- 8 1/2" native mud between cement plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

*M.R. Lamb* **M.R. Lamb** TITLE **Vice President** DATE **5-7-71**

*[Signature]* TITLE **SUPERVISOR DISTRICT 1** DATE **MAY 10 1971**

OF APPROVAL, IF ANY:

REMOVED

MAY 14 1971

OIL CONSERVATION COMM.  
HOBBS, N. M.