

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-1399

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- Disposal Well
2. Name of Operator
Marks & Garner Production Company
3. Address of Operator
P O Box 70, Lovington, New Mexico 88260
4. Location of Well
UNIT LETTER L 1370 FEET FROM THE South LINE AND 1124 FEET FROM
THE West LINE, SECTION 7 TOWNSHIP 21 RANGE 35

7. Unit Agreement Name
8. Lease or Lease Name
Shell State
9. Well No.
14
10. Field and Pool, or Village
Wilson y-SR
12. County
Lea

11. Elevation (Show whether FT, RT, GR, etc.)
3692' GE

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐
PLUG AND ABANDON ☒
CHANGE PLANS ☐
SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐
CONDUCE DRILLING OPER. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set CIBP at 3600' cap w/35 ft. cement load hole w/10# salt gel.
100 ft plug top salt. 1800' cut & pull 7 in. or perforate &
circulate. Set 50 sack plug at 127' and tag. 10 sacks at surface.

100' PLUG 50' N & 50' OUT OF CUT POINT

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNED Debra M. Moore TITLE Office Manager DATE 11-10-88
APPROVED BY Jerry Sexton ORIGINAL SIGNED BY JERRY SEXTON
TITLE DISTRICT I SUPERVISOR DATE 11-10-88
CONDITIONS OF APPROVAL, IF ANY: