## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well,

	ons of the Commission.  Indicate Nature	Zanowi by Chaolsi	na Dala		
REPORT ON BEGINNING DRILLING OPERATIONS		SULT OF TEST		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RE OPERATION	COMPLETION		REPORT ON (Other)	
	(D.	2-20-55		Artesia, New	Mexico
Following is a report on the wor	k done and the results obtain	ned under the hea	ding not	ed above at the	
Chern 611 C	***************************************	·····		(Lease)	•••••
(Contracto	Brilling Co.	, Well No2	•••••	in the	Sec11,
7 12, R 35, NMPM.,		Pool	l <b>,</b>	Los	County.
The Dates of this work were as folows:.	November 16 to	November 30	,195h	•••••	•••••••••••
Notice of intention to do the work (wa					
and approval of the proposed plan (wa			(0	cross out incorrect words)	, , , , , , , , , , , , , , , , , , , ,
• • • •					
	ILED ACCOUNT OF WOR				
Brilled hole to 3900' is Brilled out plug after of pump pressure for 30 min form 3816 to 3844. Send 20.000 lbs. send. Supbis Shiftis. After load oil	a 7 7/8 hole. Set 5 18 hours. Brilled t nutes. Held GK. Ran eiled with 10,000 ad well off and it	1/5" @3900 to 3895.Test Lame wells gallons Fam stanted flo	' viti ed vit log. eriss ving.	1 400 sacks. th 500 p s i Perforated	
Brilled hole to 3900' is Brilled out plug after of pump pressure for 30 min form 3816 to 3844. Send 20.000 lbs. send. Supplie Similarity After load of	a 7 7/8 hole. Set 5 18 hours. Brilled t nutes. Held GK. Ran eiled with 10,000 ad well off and it	1/5" @3900 to 3895.Test Lame wells gallons Fun stasted flo	' viti ed vit log. eriss ving.	1 400 sacks. th 500 p s i Perforated	
Brilled hole to 3900' is Brilled out plug after pump pressure for 30 min form 3816 to 3844. Send 20.000 lbs. send. Subbit Shirtist. After load oil (Name)	a 7 7/8 hole. Set 5 18 hours. Brilled t nutes. Held GK. Ran eiled with 10,000 ad well off and it	i 1/5" @3900 to 3895.Fest Lame wells gallons Fam started flo  a.  I hereby cert to the best of	' vitil od vit log. criss ving. Cr	A 460 seeks.  th 500 p s i  Perforated oil add  After load oil manua  the information given above is true	e and complete
Brilled hole to 3900' is Brilled out plug after pump pressure for 30 min form 3816 to 3844. Send 20.000 lbs. send. Subbit Shirtist. After load oil (Name)	7 7/8 hole. Set 5 18 hours. Brilled to mice. Held GK. Ran eiled with 10,000 at well off and it resovered, shut i	i 1/5" @3900 to 3895.Fest Lame wells gallons Fam started flo  a.  (Company)  I hereby cere	' vitil do vit log. criss ving. C	A 460 seeks.  th 500 p s i  Perforated oil add  After load oil manua  the information given above is true	e and complete