

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

SEP 20 12 41 AM '69

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-393-2	

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		
<p>1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p>		7. Unit Agreement Name
<p>2. Name of Operator Morris R. Antweil</p>		8. Farm or Lease Name Amerada State
<p>3. Address of Operator Box 2010, Hobbs, New Mexico 88240</p>		9. Well No. 2
<p>4. Location of Well</p> <p>UNIT LETTER <u>F</u> <u>1650</u> FEET FROM THE <u>North</u> LINE AND <u>2310</u> FEET FROM</p> <p>THE <u>West</u> LINE, SECTION <u>24</u> TOWNSHIP <u>21S</u> RANGE <u>35E</u> NMPM.</p>		10. Field and Pool, or Wildcat Eumont
<p>15. Elevation (Show whether DF, RT, GR, etc.) 3602' GL.</p>		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon as follows:

1. Spot 30 sx. cement plug across perfs 3786' - 3850'.
2. Load hole with mud-laden fluid.
3. Cut and pull an estimated 1500' 7" casing.
4. Spot 30 sx. cement plug across 7" casing stub.
5. Spot 30 sx. cement plug across 10-3/4" casing shoe @ 317'.
6. Spot 10 sx. surface plug with marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>R. M. Williams</u>	TITLE <u>Agent</u>	DATE <u>9-23-69</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR DISTRICT #</u>	DATE <u>SEP 25 1969</u>
CONDITIONS OF APPROVAL, IF ANY:		