

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PERORATION OFFICE	
OPERATOR	

## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

## MISCELLANEOUS NOTICES

OFFICE O. C. C.  
DEC 5 10 41 AM '63

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the school on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE	X	NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE	X	NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION  
SANTA FE, NEW MEXICORoswell, New Mexico  
(Place)December 4, 1963  
(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the

Shell Oil Company State "CN" Well No. 2-A in H  
(Company or Operator) Lease (Unit)  
SE 1/4 NE 1/4 of Sec. 24, T. 21-S, R. 35-E, NMPM, Eumont Pool  
(40-acre Subdivision)  
Lea County.

FULL DETAILS OF PROPOSED PLAN OF WORK  
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

1. Pull rods, pump and tubing.
2. Plug back with 20-40 mesh sand to 3880'.
3. Run tubing, spot 250 gallons 15% BDA with Fe additive and pull tubing.
4. Perforate with 1-3/8" JSPF @ 3842-47', 3850-58' and 3865-67'. Pressure tubing to 500 psi and shut-in overnight.
5. Let acid soak overnight and displace slowly to formation.
6. Fracture treat new perforations down 5-1/2" casing with 20,000 gallons lease crude.
7. Shut-in overnight.
8. Check for sand fill.
9. Run tubing and swab test for sand flow back.
10. Run rods and pump and place on production.

Approved....., 19.....  
Except as follows:

Shell Oil Company

Company or Operator Signed By

By R. A. Lowery R. A. LOWERY

Position District Exploitation Engineer

Send Communications regarding well to:

Shell Oil Company

Name

Box 1858

Roswell, New Mexico

Address

Approved  
OIL CONSERVATION COMMISSION

By

Title