Submit 3 Copies To Appropriate District Office District I	State of Ne Energy, Minerals and			irces				Form C-1 March 25, 19	
1625 N. French Dr., Hobbs, NM 87240 District II					WELL AP				
811 South First, Artesia, NM 87210	OIL CONSERVATION DIVISION			30-025-04439			_		
District III	2040 Sout	h Pac	heco		5. Indicate Type of Lease				
1000 Rio Brazos Rd., Aztec, NM 37410 District IV	Santa Fe, 1	NM 8	7505		STA	TE  🗴	FEE		·
2040 South Pacheco, Santa Fe, NM 87505					6. State Oi	l & Gas	Lease No.		
SUNDRY NOTIO (DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR, USE "APPLIC PROPOSALS.)	CES AND REPORTS ON DSALS TO DRILL OR TO DEE CATION FOR PERMIT" (FORM	PEN (	OR PLUG B	АСК ТО А СН	7. Lease N	ame or (	Jnit Agreem	ent Name:	
1. Type of Well: Oil Well Gas Well	Other TA'D				STATE G				
2. Name of Operator					8. Well No	• <u>•••</u> ••			-
Chevron U.S.A. Inc.					1	•			
3. Address of Operator					9. Pool name or Wildcat			-	
P.O. Box 1150 Midland, TX 7	9702				1		GRAYBURG-	ZANI ANTOPO	,
4. Well Location							CARTING OF		4
Unit Letter <u> </u>	660 feet from the	so	<b>TH</b> li	ine and	660	feet fron	the WE	<b>ST</b> lir	ne
Section 2	Township <b>21</b>	s	Range	3 <b>6</b> E	NMPM		County	T 133	
	10. Elevation (Show wh						County	LEA	
11. Check A	ppropriate Box to Ind	icate	Nature	of Notice	Penart or	Other	Doto	ි ෙැය. මාණ්තා සං දිරි	12
NOTICE OF INTE	INTION TO:	icute			=				
		<u> </u>			SEQUEN	IREP			
	PLUG AND ABANDON	X	REMEDI	AL WORK			ALTERING	GCASING	
	CHANGE PLANS		COMMEN	NCE DRILL	ING OPNS.		PLUG AN		
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING CEMENT	TEST AND JOB					
OTHER:			OTHER:						
12. Describe Proposed or Complete of starting any proposed work). or recompilation.	d Operations (Clearly state SEE RULE 1103. For Mu	e all p Iltiple	ertinent de Completic	tails, and gons: Attach	ive pertinent wellbore dia	dates, in gram of	cluding estin proposed co	nated date mpletion	

## CHEVRON PROPOSES TO PAA PER ATTACHED PROCEDURE.

	jstanti i terreta da esta da esta da esta da esta da esta da esta de esta de esta de esta de esta de esta de es Angel en esta de esta d Manda de esta d	AUST RENOTH Den by Develo Deg E R Defe	<b>માં</b> ઉત્તે હુ કર્યો દ્વનાઓ
	ن الم <sup>رور</sup> المحاد الحي الع الحي الع الع 		;
I hereby certify that the information above is true and complete to the $(1)$ $(1)$ $(1)$	he best of my knowledge and belief.		
SIGNATURE J.K. Ripley	TITLE REGULATORY O.A.	DATE_	4/24/01
Type or print name J. K. RIPLEY		Telephone No.	(915)687-7148
(This space for State use)			

APPROVEI	D BY_			
Conditions of	of appi	roval, i	if an	y

State "G" # 1 WBS # UWPWB-A10\_\_\_\_-ABN API # 30-025-04439 660' FSL & 660' FWL Section 2, T21S, R36E, UL. U Lea County, New Mexico

# Recommended P&A Procedure

### Notify OCD 24 hrs prior to operations.

- 1. This procedure will P&A the State "G" #1.
- 2. MIRU PU. Conduct Safety Meeting. Contact OCD. ND WH. NU BOP.
- 2. TOH w/tbg. RIH w/WS.
- 3. RU Sierra. Set CIBP @ 3650', cap w/ 35' sx of Cl 'C' cmt., above open hole. TAG
- 4. Perf & Sqz @ 1500' at top of Salt, spot a 100' CMT balanced plug from 1450' to 1550'. TAG
- 5. Perf & Sqz @ 1301', spot a bal. plug from 1351' 1251' at the 7-5/8" csg shoe. TAG
- 5. Perf & Sqz @ 203', spot a 100' balanced cmt plug from 253' 153', at the 10-3/4"csg shoe. TAG
- 6. Spot 10 sx Class 'C' cmt plug from 77' to surface. RD Sierra. WOC
- 7. ND BCP. RD PU. ND wellhead. Cut off casing 4' below GL & cap.
- 8. Install 4" P&A marker 4' above GL w/the following stamped on it:

Chevron U.S.A. Inc. State "G" # 1 660' FSL & 660' FWL T21S, R-36E, Sec. 4, UL U Lea County, NM

- 9. Remove all equip, deadman, and junk from location.
- 10. Fill any pits and level location.

1% CaCl (Cement Accelerator) 0.5 BA-10 (Fluid Loss Additive) 0.3 CD-32 (Cement Dispersant) 905# Brine w/25# of gel per BBL

Casing	Depth
Surf Csg	10-3/4" @ 203'
Prod Csg	7-5/8" @ 1301'
Interm. Csg.	5-1/2"@3700'
Formation Top	. Denth
Rustler	1270'
Top Of Salt	1500'
Base of Salt	2520'
Yates	2730'
Class (	

CJ Affeld Petroleum Engineer CTN 687-7271 Home – 915-694-3884 Chevron

# Proposed P&A WELL DATA SHEET

