


N.M.O.C.C.
November 4, 1966
Page 2.

Our conclusions are as follows:

- A. This well does not have any escape of gas from the well bore.
- B. The communication between the strings is caused by a bad packing gland between the casing and the bradenhead.
- C. Since there is no escape of gas from the well bore, we shall leave the well head in its present condition.

Enclosed you will find a copy of the temperature log we ran on this well. Should you desire any other information, or any other investigation, please notify us.

Sincerely,


John A. Disch

JAD/jan

Enclosure