

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	WELL API NO. 30-025-04446
2. Name of Operator Chevron USA, Inc.	5. Indicate Type of Lease STATE ☒ FEE ☐
3. Address of Operator 15 Smith Rd., Midland, Texas 79705	6. State Oil & Gas Lease No.
4. Well Location Unit Letter <u>W</u> : <u>660</u> feet from the <u>South</u> line and <u>1980</u> feet from the <u>East</u> line Section <u>2</u> Township <u>21S</u> Range <u>36E</u> NMPM Lea County	7. Lease Name or Unit Agreement Name: Eunice Monument South Unit
8. Well No. <u>268</u>	
9. Pool name or Wildcat Eunice Monument, Grayburg -SA	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

II. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Notify OCD 24 hrs prior to MI & RU.
2. Set 7" CIBP @ 3600', (Grayburg- San Andres) Spot 40 Sx plug 3600'-3400' (Queen) WOC Tag.
3. Displace hole w/MLF, 9.5# Brine w/25# Gel P/BBL.
4. Spot 40 Sx plug 2600'-2400' (9 5/8" Shoe, B-Salt) WOC Tag.
5. Cut 7" Csg @ 1250', L/D Csg.
6. Spot 75 Sx plug 1350'-1100', (T-Salt, Stub) WOC Tag.
7. Spot 75 Sx plug 350'-150' (13" Shoe) WOC Tag.
8. 10 Sx Surface, Install dry hole marker.

THIS DOCUMENT IS NOT FOR THE
PUBLIC. IT IS THE PROPERTY OF
THE NEW MEXICO DEPARTMENT OF
ENERGY, MINERALS AND NATURAL
RESOURCES. IT IS TO BE KEPT
CONFIDENTIAL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE A.R. Bledsoe TITLE HES Specialist DATE 5/31/2002

Type or print name G.R. Bledsoe Telephone No. 915. 687.7153

(This space for State use)

APPROVED BY GARY W. WINK
OC FIELD REPRESENTATIVE II/STAFF MANAGER
Conditions of approval, if any:

JUN 04 2002
DATE

PLUGGING & ABANDONMENT WORKSHEET

OPERATOR CHEV N USA Inc.
 LEASE NAME EUNICE MOWMENT SOUTH UNIT
 WELL # 268

SECT 2 TWN 21-S RNG 36-E
 FROM 660 NSL 1980 EWL
 TD 3849 FORMATION @ TD SAN-ANDRES
 PBTD FORMATION @ PBTD Grayburg

	SIZE	SET @	TOC	TOC DETERMINED BY
SURFACE	13"	297	SURF	Circ
INTMED 1	9 5/8	2522	260	CALC
INTMED 2				
PROD	7"	3669	1562	CALC

	SIZE	TOP	BOT	TOC	DETERMINED BY
LINER 1					
LINER 2					

	CUT & PULL	TOP - BOTTOM
INTMED 1	PERFS	
INTMED 2		
PROD	OPENHOLE	3669 - 3849

*REQUIRED PLUGS DISTRICT

	PLUG	TYPE PLUG	SACKS CEMENT	DEPTH
RUSTLER (ANHYD)	1	CIBP		3600
YATES	2	QUEEN	40	3600
QUEEN	3	9 5/8 SHOE	40	2600
GRAYBURG	4	T-SALT	75	1300
SAN ANDRES	5	13" SHOE	75	350
CAPITAN REEF	6	SURF	10	10
DELAWARE				
BELL CANYON				
CHERRY CANYON				
BRUSHY CANYON				
BONE SPRING				
GLORIETA				
BLINBRY				
TUBB				
DRINKARD				
ABO				
WC				
PENN				
STRAWN				
ATOKA				
MORROW				
MISS				
DEVONIAN				

MLF

13"

@ 297

TOC SURF

MLF

9 5/8

@ 2522

TOC 260

MLF

MLF

7"

@ 3669

TOC 1562

TD 3849