

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
Chevron U.S.A. Inc.

Address of Operator
P.O. Box 670 Hobbs, NM 88240

Location of Well

UNIT LETTER U 660 FEET FROM THE South LINE AND 660 FEET FROM
THE West LINE, SECTION 3 TOWNSHIP 21S RANGE 36E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3572

7. Unit Agreement Name
Eunice Monument South

8. Farm or Lease Name Unit

9. Well No.
262

10. Field and Pool, or Wildcat
Eunice Monument G/SA

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

ORM REMEDIAL WORK ☐
PERMANENTLY ABANDON ☐
OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIATION WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER sqz zones 1-4, recomp zones 1-3 ☒
ALTERING CASINGS ☐
PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Work performed 4-9-88 thru 4-17-88

TD. 3885 PB. 3850

POOH w/ production equipment. Set 5½" cmt ret on wireline at 3550'. Load hole w/CBW, test tbq to 3000psi. Cmt w/ 100sx C1 C, tail w/ 300sx C1 C neat. Formation taking cmt at 1/2bpm on vacuum at end of 70 min hesitation. PO cmt ret. DO cmt ret and 30' green cmt to 3580'. WOC. DP cmt f/3581' to 3660'. Test csg to 500psi, ok. DO cmt f/3660' - 3675'. Test csg and sqzd perf at 3668-70 to 500psi, ok. DO cmt f/3675-3727'. Tst csg and sqz perf at 3686-3722 to 500psi, ok. DO cmt f/3727-3778. Tst csg and sqz perf at 3731-3778 to 500psi, lost 400psi in 4 min. DO cmt f/3778-3820'. Drlg cmt stringers f/3808 to bottom of cmt at 3820'. Tst csg to 500psi. Lost 350psi in 4 min. POH w/ BHA. SD. GIH and set pkr at 3716'. Swab test sqz work. Perf w/4" guns, 1 CJPF, phased 180° 5 holes in Eunice Mon. Grayburg zone #3. f/3767-3772'. Tst tbq to 3000psi, ok. Set pkr at 3742', acdz perfs in zone 3 w/400gal 15% NEFEHCL. Flush w/ CKF. Swab. PU RBP & pkr, gih to 3753'. Set and test RBP to 500psi, ok. Perf w/ 4" guns 1 CJPF, 120°, 41 holes in zones 1 & 2 at 3668-70, 3686-88, 3692-94, 3698-3723 and 3731-41. Spot 100 gal 15% NEFE, f/3740-3640'. POOH and set pkr at 3592, Acdz perfs in zones 1 & 2 w/2000 gall. 15% NEFE HCL. Block w/ 50-7/8" RCNB's Flush w/ 24 bbls CKF to btm prf. Swab. Run production tbq (continued)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

M. E. Ahern

TITLE Staff Drilling Engineer

DATE April 29, 1988

Orig. Signed by
Paul Kautz
Geologist

DATE BY _____

TITLE _____

DATE MAY 4 - 1988

CONDITIONS OF APPROVAL, IF ANY: