

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLIC.  
(Other instructions on  
reverse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS 8821

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

NAME OF OPERATOR

Chevron U.S.A. Inc.

ADDRESS OF OPERATOR

P.O. Box 670, Hobbs, New Mexico 88240

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)

At surface

Unit I, 3233' FNL & 660' FEL

4620/8

4. PERMIT NO.

15. ELEVATIONS (Show whether OF, RT, GR, etc.)

3538

5. LEASE DESIGNATION AND SERIAL NO.

LC031740B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Eunice Monument South Unit

8. FARM OR LEASE NAME

9. WELL NO.

208

10. FIELD AND POOL, OR WILDCAT

Eunice Monument G/SA

11. SEC. T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 4, T21S, R36E

12. COUNTY OR PARISH 13. STATE

Lea

NM

6. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PCLL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)

6-21-87 TOH w/prod. tbg. Perf open hole 3740-3820, PU BHA, and TIH  
w/ 2 7/8 WS to 3751'. Break circ w/ air mist. Clean out fill 3800'  
to PBTD 3843'. Circ hole clean. TOH w/ BHA. TIH w/Western R Pkr  
and 2 7/8 WS. Leave set at 3636. Acidize Open hole 3727-3843 w/  
3500 gallons 15% NEFE HCL flushed w/27 bbls CBW, RIH w/prod equip.  
dump 5 gallond corrosion inhibitor down tbg. Hang well on Tst pmp  
to 500psi, OK. Work performed 6-21-87 through 6-22-87.

ACCEPTED FOR RECORD

JUL 10 1987  
SJS

CARLSBAD, NEW MEXICO

RECEIVED  
JUL 9 11 09 AM '87  
CARLSBAD RESOURCE  
AREA HEADQUARTERS

I hereby certify that the foregoing is true and correct

SIGNED M. E. Abrin TITLE STAFF DRILLING ENGINEER DATE JULY 6, 1987

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side