Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revisied 1-1-89

OIL CONSERVATION DIVISION

District Office		·	IL CONSERVA		V					
DIOTRICT (P.O. Bo		2000					
DISTRICT I	Habba NM 99340		Santa Fe, Nev	w Mexico 87504-	2088					
DISTRICT II	O. 8ox 1980, Hobbs, NM 88240 ISTRICT II						API NO. (assigned by OCD on New Wells)			
P.O. Drawer Dd	Drawer Dd, Artesia, NM 88210						30-025-04488			
DISTRICT III	TRICT III						pe of Lease			
1000 Rio Brazo	s Rd., Aztec, Nm 87	410					STATE [∑ FEE	E 🗀	
						6. State Oil &	Gas Lease No.			
							N/A			
SUNDRY NOTICES AND REPORTS ON WELLS										
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A							7. Lease Name or Unit Agreement Name			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)							ISAY (NCT-A)			
1. Type of We	ell:	(FORM C-10)	I) FOR SUCH PROPOSAL	5.) 		4				
OIL		GAS				}				
WELL		WELL X	OTHER							
2. Name of Op		S A INC				B. Well No.				
CHEVRON U.S.A. INC.							9. Pool name or Wildcat			
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS						EUMONT				
4. Well Location									_	
Unit Letter	4	<u> </u>	660 Feet From The	SOUTH	Line and		60 Feet From The	WEST		
Section	4 ////////////////////////////////////		Township 10. Elevation(21S Show whether DF, RKB, RT,	Range GR. etc.)	36E	NMPM L	.EA	County	
				3583' GE	J., 515.,					
11		Check Approp	riate Box to Indecate Nati	ure of Notice, Report, or	Other Data					
	NOTICE OF I	NTENTION TO:			QUENT RE	PORT OF:				
PERFORM REME	EDIAL WORK	PLUG AND ABA	NDON	REMEDIAL WORK		7	ALTER CASING			
TEMPORARILY .	ABANDON	CHANGE PLANS	s 🗍	COMMENCE DRILLING OPN	ıs.]	PLUG AND ABAN			
PULL OR ALTER	CASING			CASING TEST AND CMT JO	ов 🗔					
OTHER:				OTHER: PERF, AC	DZ & FRA	λīc			X	
12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including										
esticated date of starting any proposed work) SEE RULE 1103.										
	TILL AND CLE	EAN OUT TO T	D CHANGE OUT W	ELLUEAD AND INC	TALL 7 1	/16' V E 1/	27 284			
	TIH AND CLEAN OUT TO TD. CHANGE OUT WELLHEAD AND INSTALL 7 1/16' X 5 1/2", 3M.									
ACDZ PERFS 3350-5495 WITH 450 GALS OF 15% NEFE, SWAB BACK.										
	PERF 3308-12 & 3326-32, 60 DEG PHSD, 4" GUNS. RAN CBL, TOC AT 2612'.									
ACDZ WITH 600 GALS OF 15% NEFE, SWAB BACK.										
	TIH WITH PACKER AND SET AT 3230, INSTALL FRAC TREE.									
	FRAC PERFS AT 3308-3495 WITH 1059 BBLS OF GELLED WATER AND 164 TONS OF CO2.									
	85,500# OF 12/20 BRADY SAND, 46,500# OF 8/16 SAND, 25,000# OF ACFRAC CC SAND.									
	FLOWED WELL BACK. TIH WITH COIL TBG. AND CLEANED OUT TO TD.									
	FLOW WELL BACK, POOH WITH FRAC STRING.									
	TIH WITH PRODUCTION TBG, LOADED BACK SIDE.									
	RETURN TO PRODUCTION ON 6-21-92.									
I hereby certify	that the information	shove is true and comp	plete to the best of my knowled							
SIGNITURE	P.18	Matthe	m TITLE	TECH. ASSISTAN	<u>T</u>	DATE:	6-23-92		 .	
TYPE OR PRINT	NAME	P.R. MATT	HEWS			TELEPHONE NO	o. (915)687-7	812		
			r m sag cons							
APPROVED BY			TITLE			DATE	• .			
	F APPROVAL, IF AN	IY:								