Submit 3 Copies to Appropriate State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION

Form C-103 Revisied 1-1-89

District Office

CONDITIONS OF APPROVAL, IF ANY:

		P.O. B	ox 2088			
DISTRICT I	S	anta Fe, Ne	w Mexico 87504-2088			
P.O. Box 1980, Hobbs, NM	88240			Legista di salara	d his OCO on Nove Wellet	
DISTRICT II				API NO. (sesigned by OCD on New Wells)		
P.O. Drawer Dd, Artesia, NN DISTRICT III	1 88210			5. Indicate Typ		
1000 Rio Brazos Rd., Aztec, Nm 87410					STATE X	FEE
				6. State Oil &	Gas Lease No.	
				N/A		
SUNDRY NOTICES AND REPORTS ON WELLS						
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					or Unit Agreement Name	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)				DEEL NAME	OLI NOT A	
1. Type of Well:	(FORM C-101) FOR S	OGIT THO TOOK		_		
OIL	GAS			ė		
WELL	WELL X OTT	HER				
2. Name of Operator	ON LL C A INC			8. Well No.	8	
3. Address of Operator	ON U.S.A. INC.			9. Pool name		
P.O. BOX 1150 M	IDLAND, TX 79702 ATTN	NITA RICE		EUMONT	GAS POOL	
4. Well Location	A		na SOUTH Line and	6/	60 Feet From The WI	EST Line
Unit Letter	1 3 2 3 40	20 Feet From Th	SOUTH Line and 21 SOUTH Range	36E	NMPM LEA	County
Section Section			on(Show whether DF, RKB, RT, GR, etc.)			
			3570' GR			
11		k to Indecate Na	ature of Notice, Report, or Other Data			
NOTICE	OF INTENTION TO:		SUBSEQUENT R	REPORT OF:		<del></del>
PERFORM REMEDIAL WORK	PLUG AND ABANDON	<u> </u>	REMEDIAL WORK	_	ALTER CASING	$\vdash$
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING OPNS.	<b>_</b>	PLUG AND ABAN.	
PULL OR ALTER CASING		<del></del>	CASING TEST AND CMT JOB			F7
OTHER: ADD PI	ERFS,ACDZ & FRAC	X	OTHER:			
		deseile and	nice partinger dates including			
12. Describe Proposed or t esticated date of startin	Completed Operations(Clearly state all peg any proposed work) SEE RULE 1103.	runent details, and	give perturbin detes, accounty			
	OPOSE TO:					
FRAC I	EXISTING PERFS 3355-352	20 WITH 41,	250 GALS & 152,000 LBS S	AND. FLOW	& SWAB BACK LOA	۱D.
KILL W	ELL. ADD PERFFS 3005-3	1086 (18 HO	LES) IN SEVEN RIVERS. ACT	oz WITH 900	GALS &	
FRAC \	N/39,750 GALS & 152,00	O LBS SAND	). FLOW & SWAB BACK LOA	D. RUN PROI	D TBG TO 3325, NO	BOP &
PLACE	WELL ON PRODUCTION.					
	^					
I hereby certify that the info	ormation above is true and complete to the	ne best of my know		DATE:	00/23/04	<del></del>
SIGNITURE	lila Rice	TITLE	TECHNICAL ASSISTANT	DATE:	08/23/94	
TYPE OR PRINT NAME	NITA RICE	_		TELEPHONE N	o. (915)687-7436	
		C	) Fire Signad un		NED () 4 4004	
ADDROVED SV		TITLE	Chologiat	DATE	SEP 0 1 1994	
APPROVED BY			THE HIVE TO			

RECENTO

AUC 1 1894

THE WHITE