

NEW MEXICO STATE LAND OFFICE
SANTA FE, NEW MEXICO

STATE "E" #2

DEPARTMENT OF THE STATE GEOLOGIST
NOTICE OF INTENTION TO TEST WATER SHUT-OFF

Notice must be given to the State Geologist or to the proper Oil and Gas Inspector at least five days before the test. It is desirable that a representative of the Department of the State Geologist witness the water shut-off before drilling into the productive sand whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to sender. Submit this notice in triplicate.

Dallas, Texas.NOV 2, 1935, 1935Mr. F. J. Vesely,State ~~Geologist~~ Oil & Gas Inspector,Carlsbad, ~~Santa Fe~~, New Mexico.

Dear Sir:

You are hereby notified that we intend to test the shut-off of water in State "E"Well No. 2 in SW/4 of Sec. 5, T. 21 South, R. 36 EastN. M. P. M., Bunice Oil Field Lea County,on 10/7 19 35 8-5/8 in. 32 lb. casing was { cemented { in Shaleformation at a depth of 1547 feet on 10/4 19 35700 sacks of Incor cement were used.

The method used in placing the cement was as follows:

Fluid level will be bailed to a depth of _____ feet and left undisturbed for at least 12 hours before your inspection.

Adjacent property owners have been notified as follows: Ohio and Gypsy

Additional information:

Tested 8-5/8" casing -- 1200' cold water test by Halliburton.

Approved _____ 19____

Except as follows:


Sincerely yours,

ATLANTIC OIL PRODUCING COMPANYBy La Beecher Company or Operator.Position Drilling & Production Department

Send communication regarding well to

Name Above

Address _____


State Geologist or Oil and Gas Inspector.

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000

100-100000-100000