| DISTRIBUTION | | 13 | Supersedes Old C-102 and C-103 |
|--|--|--|--|
| ITA FE | NEW MEXICO OIL CONSE | ERVATION COMMISSION | Effective 1-1-65 |
| E | | JUN | 5g. Indicate Type of Lease |
| .G.S. | | -11 | Stee Type of Lease |
| ND OFFICE | | | 5. State Oil & Gas Lease No. |
| ERATOR | | | B-1641-4 |
| SUN (DO NOT USE THIS FORM FOR USE "APPLI | DRY NOTICES AND REPORTS ON PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACATION FOR PERMIT - " (FORM C-101) FOR SUCF | WELLS ACK TO A DIFFERENT RESERVOIR. | |
| OIL GAS | | | 7. Unit Agreement Name |
| well well well well | ОТНЕЯ- | | 8. Farm or Lease Name |
| oil Corporation | | | Heasley State |
| ddress of Operator | | | 9. Well No. |
| x 670, Hobbs, New P | lexice 88240 | | 10. Field and Pool, or Wildcat |
| ocation of Well | 1:100 | *** | |
| UNIT LETTER,_ | 1980 FEET FROM THE North | LINE ANDFEET F | ROM CONTRACTOR |
| THE WEST LINE SE | ction 5 township 21-5 | RANGE 36-E N | 1PM. |
| THE WEST LINE, SE | CTIONTOWNSHIP | RANGE 10-6 N | |
| | 15, Elevation (Show whether | DF, RT, GR, etc.) | 12. County |
| | | 3573' DF | Ica ())))) |
| | ek Appropriate Box To Indicate N | | Other Data ENT REPORT OF: |
| | | · | |
| FORM REMEDIAL WORK | PLUG AND ABANDON | REMEDIAL WORK | ALTERING CASING |
| PORAR(LY ABANDON | | COMMENCE DRILLING OPNS. | PLUG AND ABANDONMENT |
| | , , , | | |
| L OR ALTER CASING | CHANGE PLANS | CASING TEST AND CEMENT JQB | |
| | CHANGE PLANS | CASING TEST AND CEMENT JQB | |
| Plug Back Describe Proposed or Complete | CHANGE PLANS d Operations (Clearly state all pertinent deta | OTHER | ding estimated date of starting any proj |
| Plug Back Describe Proposed or Complete Pork) SEE RULE 1103. Plans have | | other | oximately 3875' with |
| Plans have irenite. If necess I hereby certify that the inform ORIGINAL Sic. D. BOR | been made to plug back 6-1 sary, treat with 500 gallon ation above is true and complete to the best enem by | other | eximately 3875' with turn well to production |
| Plug Bock Describe Proposed or Complete work) SEE RULE 1103. Plans have remite. If necess I hereby certify that the inform ORIGINAL Sie | been made to plug back 6-1 sary, treat with 500 gallon ation above is true and complete to the best enem by | of my knowledge and belief. | eximately 3875' with turn well to production |
| Plans have irenite. If necess I hereby certify that the inform ORIGINAL Sic. D. BOR | been made to plug back 6-1 sary, treat with 500 gallon ation above is true and complete to the best enem by | of my knowledge and belief. | eximately 3875' with turn well to production |