

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator Chevron USA, Inc.	6. State Oil & Gas Lease No.
3. Address of Operator 15 Smith Rd., Midland, Texas 79705	7. Lease Name or Unit Agreement Name: Eunice Monument South Unit
4. Well Location Unit Letter <u>D</u> : <u>660</u> feet from the <u>North</u> line and <u>660</u> feet from the <u>West</u> line Section <u>6</u> Township <u>21S</u> Range <u>36E</u> NMPM <u>Lea</u> County	8. Well No. 191
9. Pool name or Wildcat Eunice Monument Grayburg San Andres	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	MULTIPLE COMPLETION ☐	CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Notify OCD 24 hrs prior to MI & RU.
2. Set 5 1/2" CIBP @ 3675', (Grayburg-San Andres) Spot 30 Sx plug 3675'-3400' (Queen) WOC Tag.
3. Displace hole w/MLF, 9.5# Brine w/25# Gel P/BBL.
4. Spot 25 Sx plug 2600'-2400' (B-Salt) WOC Tag.
5. Spot 25 Sx plug 1300'-1100' (8 5/8" Shoe, T-Salt) WOC Tag.
6. Spot 40 Sx plug 350'-Surf (12 1/2" Shoe, Surface) - TAG
7. Install dry marker.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE G. R. Bledsoe TITLE HES Specialist DATE 5/27/2002
Type or print name G. R. Bledsoe Telephone No. 915.687.7152
(This space for State use)

APPROVED BY _____ TITLE _____ DATE _____
Conditions of approval, if any:
ORIGINAL SIGNED BY
GARY W. WINK
OC FIELD REPRESENTATIVE II/STAFF MANAGER

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

LOGGING & ABANDONMENT WORKSHEET

OPERATOR CHE IN USA Inc
 LEASE NAME EMICE MOUNTAIN SOUTH UNIT
 WELL # 191

SECT 6 TWN 21-S RNG 36-E
 FROM 660 (N)SL 660 E(W)L 660
 TD 3850 FORMATION @ TD SAN ANDRES
 PBTD 660 FORMATION @ PBTD GRAYBURG

12 1/2
 @ 285
 TOC SURF

8 5/8
 @ 1250
 TOC SURF

5 1/2
 @ 3728
 TOC SURF

TD 3850

	SIZE	SET @	TOC	TOC DETERMINED BY
SURFACE	<u>12 1/2</u>	<u>285</u>	<u>SURF</u>	<u>Circ</u>
INTMED 1	<u>8 5/8</u>	<u>1250</u>	<u>SURF</u>	<u>Circ</u>
INTMED 2				
PROD	<u>5 1/2</u>	<u>3728</u>	<u>SURF</u>	<u>Circ</u>

	SIZE	TOP	BOT	TOC	DETERMINED BY
LINER 1					
LINER 2					

	CUT & PULL	TOP - BOTTOM
INTMED 1		PERFS
INTMED 2		
PROD		OPENHOLE <u>3728 - 3850</u>

*REQUIRED PLUGS DISTRICT

	PLUG	TYPE PLUG	SACKS CEMENT	DEPTH
RUSTLER (ANHYD)	1	CIBP		3675
YATES	2	QUEEN	30	3675
QUEEN	3	B-SALT	25	2600
GRAYBURG	4	8 5/8 SHOE	25	1300
SAN ANDRES	5	12 1/2 SHOE	40	350
CAPTAN REEF				
DELAWARE				
BELL CANYON				
CHERRY CANYON				
BRUSHY CANYON				
BONE SPRING				
GLORIETA				
BLINBRY				
TUBB				
DRINKARD				
ABO				
WC				
PENN				
STRAWN				
ATOKA				
MORROW				
MISS				
DEVONIAN				