STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION	
BANTA FE	- - -
PILE	
LOTO.	
LANG OFFICE	
TRAMEPORTER CI	-11
	. 1 1
POTATOR	
PROBATION OFFICE	

OIL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE. NEW MEXICO 87501

Form C-104 Revised 10-01-78 Format 06-01-83 Page 1

REQUEST FOR ALLOWABLE

PERATOR	KELUEST :	FOR ALLOWABLE		. 296
PROMATION OFFICE	ALITHOPIZATION TO TO	AND	•	¥2%
Cperator	AUTHORIZATION TO TRA	NSPORT OIL AND NAT	URAL GAS	4. igen ∮ ™ (
				
Chevron U. S. A. Inc	•	· · · · · · · · · · · · · · · · · · ·		
P. O. 670, Hobbs, New	W Mexico 88240	•		·
Reason(s) for filing (Cheek proper box)		100		
New Well	Change in Transporter of:	Other (Plea	se explainj	
Recompletion	<u> </u>	Dry Gas Split	Connection on both oi	1 & gas
Change in Ownership	Casinghead Gas	Condensate		_ 4 640
If change of ownership give name and address of previous owner				
			·	-
II. DESCRIPTION OF WELL AND	Well No. Pool Name, Including	·		
Eunice Monument South Uni	12/21		Kind of Lease	Ledec No.
Location Continuent South Offi	t 292 Eunice Monume	ent G-SA	State, Federal or Fee	2,000
Unit Lotter (2 . 198	Deer From The Morth	1000		<u>-</u>
= 1.701	2 Feet From The 1 Wille	ine and	_ Feet From The Cast	
Line of Section Townsh	nip 2/5 Range	36E . NMPM	•	Lea
	•			County
Name of Authorized Transporter of Cil T	TER OF OIL AND NATURA	L GAS		•
		Adaress (Give address	o which approved copy of this form is	s to be sent)
Name of Authorized Transporter of Cappy		1		
Warren Petroleum & Philli	N-0030001 poremen -	VF. February 1. 19	a which approved copy of this form is	s to be sent!
Il well produces oil or liquide.	II Sec. Twp. 'Ree.	Is que actually connects		
give location of tanks.	n: 4 215 36F	VAS		ď
If this production is commingled with th	at from any other lease or pool	yes	unknown	<u> </u>
NOTE: Complete Parts IV and V and	and the second poor.	give commingling order	number:	
NOTE: Complete Parts IV and V on	reverse side if necessary.			
VI. CERTIFICATE OF COMPLIANCE		اا ما در		
I hereby certify that the sulm and and in	6 1 .		INSERVATION DIVISION	
I hereby certify that the rules and regulations of seen complied with and that the information given my knowledge and belief	the Oil Conservation Division have	APPROVED	AA: 0 1987	90
ny knowledge and belief.	and and complete to the best of	BY OBSIDA	THE TWO ISSUES	
	·	DICTOL	ENER BY JERRY SEXTON	
Ω · Ω		TITLE DISTRI	CT I SUPERVISOR	
Chron (1)	0.011	This form is to !	oe filed in compliance with AUL	
(Signature)	for C/M	II this is a reque	at for allowable for a second disc	
New Mexico Area Superinter	ident			
(Title)		All sections of the	is for such by dividing the	1.
	·		mbrated metter	
(Date)		Fill out only Ser well name or number,	ctions I. II. III. and VI for char or transporter, or other such chang	nges of owner.
		Separate Forms	a memobourar or other anch cheut	ge of conditions

Separate Forms C-104 must be filed for each pool in multiply completed wells.

Form C-104 Revised 10-01-78 Format 06-01-83 Page 2

IV. COMPLE	TION DATA			-					•	
Designati	Type of Complete	ion - (X)	Meil	Gas Well	New Well	Workover	Deepen	Plug Back	Same Resty	Diff. Re
Date Spuaded		Date Compt. R	leday to P	rod.	Total Depth	<u>; </u>	<u> </u>	P.B.T.D.	<u>.</u>	4
Elevations (DF	RKB. RT. GR. etc.,	Name at Produ	cing Form	ation	Top CII/Ga	E Pay	+20-2	Tuoing Dep	in ; e	
Pertorations		<u>_'</u>			0.	ים בי	tt _ (Depth Casts	ng Shoe	
		T	UBING, C	ZASING, AND	CEMENTI	IC PECOPE	· · · · · · · · · · · · · · · · · · ·	<u>!</u>		
н	LE SIZE			IG SIZE		DEPTH SE		1	CYE CEUE	
		·					SACKS CEMENT -			
										
		<u> </u>								
		!			i			†		
		FOR ALLOW.	ABLE OF	est must be a ble for this de	iter recovery a pth or be for f	f total volum ull 24 hours)	e of load all	ind must be eq	tual to or exc	eed top all
Date First New	Ott Run To Tenks	Date of Teet			Producing Method (Flow, pump, gas lift, stc.)					
Length of Test		Tuning Pressur	•		Casing Pres	sure ·		Chore Size		
Actual Prod. Du	and Test	O11 - 8 b1 a.			Water - Bbis.			Gas-MCF		•
AS WELL								<u></u>		
Actual Prod. To	- MCF/D	Length of Test			Bhis. Conder	ieate/MMCF		Gravity of C	ondenegte	
Testing Method	Agust, hace prof	1 = 101 = 0 = 0	. / =				· · · · · · · · · · · · · · · · · · ·	-		
	, , , , , , , , , , , , , , , , , , ,	Tubing Pressure	(Epite-F	. (.	Casing Press	me (2par-T	_	Chore Size		
	 	<u>!</u>								