NO. OF COPIES RECEIVED]	÷	
DISTRIBUTION		HORES OFF	Form C-103 Supersedes Old
SANTA FE		SERVATION COMMISSION	D. C. C ⁻¹⁰² and C-103
FILE		lier 21 p	Effective 1-1-65
U.S.G.S.		22021 J 31 P	W PEF Indicate True of Land
LAND OFFICE		HOLDS OFFICE (SERVATION COMMISSION DEC 21 3 31 P	
OPERATOR			5. State Oil & Gas Lease No.
	1		5. State Off & Gds Ledse No.
(DO NOT USE THIS FORM FOR PRO USE "APPLICAT 1. OIL WELL WELL	Y NOTICES AND REPORTS ON POSALS TO DRILL OR TO DEEPEN OR PLUG E ION FOR PERMIT -" (FORM C-101) FOR SUC	WELLS BACK TO A DIFFERENT RESERVOIR. CH PROPOSALS.)	7. Unit Agreement Name
2. Name of Cperator	OTHER-		
Cult Ctl Commencetton			8, Farm or Lease Name
Onlf Oil Corporation 3. Address of Operator			Mollie Campbell
Box 670, Hobbs, New Me 4. Location of Well	xico		9. Well No.
	660 FEET FROM THE South	1980	10. Field and Pool, or Wildcat
	7 TOWNSHIP		
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	15. Elevation (Show whether	DE DT CD	
		·	12. County
	3622		
Check A	Appropriate Box To Indicate N	lature of Notice, Report or O	other Data
NOTICE OF IN	TENTION TO:	SUBSEQUER	NT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🍂	REMEDIAL WORK	
TEMPORARILY ABANDON		COMMENCE DELLING OPNS.	ALTERING CASING
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
OTHER Plug and abandon		OTHER	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3925' TD, 3303' PB. (Well is plugged back from 3861' to 3303' with cement.) It is proposed to plug and abandon as follows: Run tubing to bottom. Circulate hole with 80 barrels of mud. Pall tubing to 50' and spot 50' (10) sacks) cement plug to surface. Clean location and install dry hole marker.

(See attachment)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED	TITLE Area Production Man	ager December 20, 1965
APPROVED BY		