STATE UP NEW MEXICO ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION		
SANTA FE		
FILE		Γ.
U.1.G.5.		
LAND OFFICE		
OPERATOR	$\overline{}$	

UIL CONSERVATION DIVISION

	P. O. BOX 20		Revised 10
FILE	SANTA FE, NEW ME	XICO 875Q1	•
U.S.G.S.	3		Sa. Indicate Type of Lease
LAND OFFICE			State X Fee
OPERATOR			5, State Oil & Gas Lease No.
	RY NOTICES AND REPORTS ON WELL		
well Well D		, osacs.)	Eunice Monument
Chevron U.S.A	Tnc .	· · · · · · · · · · · · · · · · · · ·	8. Form or Lease Hame
ddress of Operator	11101		9. Well No.
	Hobbs, NM 88240		323
ocation of Well T 1	090 South	660	10. Field and Pool, or Wildcat
UNIT LETTER I	980 FEET FROM THE South	ME AND 660 PEET	Eunice Monument
THE East LINE, SECT	TOW 8 TOWNSHIP 21S	36E	
	15. Elevation (Show whether DF, R 3608 GL	T, GR, etc.)	12. County Lea
Check	Appropriate Box To Indicate Natur	e of Notice Report of	
NOTICE OF	NTENTION TO:		JENT REPORT OF:
-	PLUE AND ABANDON ASM		1 .
PORARILY ASAMDON	. —	MENCE DRILLING OPHS.	ALTERING CASING
		MENCE DRICCING DPHS.	PLUS AND ABAHOOHMEN
L DA ALTER CABING		HE TEST AND SEMENT ION	
Class out and Dec	CASI	HE TEST AND CEMENT JQB	
Clean out and Dee	pen 📉 🗀	THER	uding estimated date of starting any pro
Clean out and Dee	CASI	nd give persinent dates, incl Acidize open hole	
Clean out and Dee	pen CASI Perations (Clearly state all pertinent details, a en well to 4050'. Log well.	nd give persinent dates, incl Acidize open hole	
Clean out and Dee	pen CASI Perations (Clearly state all pertinent details, a en well to 4050'. Log well.	nd give persinent dates, incl Acidize open hole	
Clean out and Dee	pen CASI Perations (Clearly state all pertinent details, a en well to 4050'. Log well.	nd give persinent dates, incl Acidize open hole	
Clean out and Dee	pen CASI Perations (Clearly state all pertinent details, a en well to 4050'. Log well.	nd give persinent dates, incl Acidize open hole	
Clean out and Dee	pen CASI Perations (Clearly state all pertinent details, a en well to 4050'. Log well.	nd give persinent dates, incl Acidize open hole	
Clean out and Dee	pen CASI Perations (Clearly state all pertinent details, a en well to 4050'. Log well.	nd give persinent dates, incl Acidize open hole	
Clean out and Dee	pen CASI Perations (Clearly state all pertinent details, a en well to 4050'. Log well.	nd give persinent dates, incl Acidize open hole	
Clean out and Dee	pen CASI Perations (Clearly state all pertinent details, a en well to 4050'. Log well.	nd give persinent dates, incl Acidize open hole	
Clean out and Dee	pen CASI Perations (Clearly state all pertinent details, a en well to 4050'. Log well.	nd give persinent dates, incl Acidize open hole	
Clean out and Dee	pen CASI Perations (Clearly state all pertinent details, a en well to 4050'. Log well.	nd give persinent dates, incl Acidize open hole	
Clean out and Dee	pen CASI Perations (Clearly state all pertinent details, a en well to 4050'. Log well.	nd give persinent dates, incl Acidize open hole	
Clean out and Dee	pen Apperations (Clearly state all persinent details, a en well to 4050'. Log well. rell. Equip to pump. Return	Acidize open hole to production.	
Clean out and Dee	pen CASI Perations (Clearly state all pertinent details, a en well to 4050'. Log well.	Acidize open hole to production.	