Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department **OIL CONSERVATION DIVISION**

Form C-103 Revisied 1-1-89

District Office

		P.O. Bo	x 2088									
DISTRICT I	Sa	nta Fe, Nev	v Mexico	87504-2	088							
P.O. Box 1980, Hobbs, NM 88240				0,00.2	-							
DISTRICT II						API NO. (a	esigned by (OCD on New V	Vellsi			
P.O. Drawer Dd, Artesia, NM 88210							30-025-04564					
DISTRICT III						5. Indicat	te Type of Lo	0.800				
1000 Rio Brazos Rd., Aztec, Nm 87410							S	TATE [FEE	X		
						6. State	Oil & Ges Le	sass No.				
							N/A					
SUNDRY NOTICES AND REPORTS ON WELLS												
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"						7. Lesse Name or Unit Agreement Name R. R. BELL (NCT-A) COM						
(FORM C-101) FOR SUCH PROPOSALS.)								,	•			
1. Type of Well:						┪						
OIL	GAS											
WELL	WELL X OTHE	R										
2. Name of Operator						8. Well N	lo.					
CHEVRON U.S	S.A. INC.					2						
3. Address of Operator						9. Pool name or Wildcat						
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE					EUMO	NT						
4. Well Location Unit Letter	● P : 66	O Feet From The		SOUTH	Line and		660 sa	et From The	EAST	Line		
Section 8		Township	21S		Renge	36E			LEA	County		
		10. Elevation	Show whether	DF, RKB, RT, G	-		7///		illinitaniin	eraintiiiilliili		
				3606' GL								
11	Check Appropriate Box 1	o Indecate Nati	ure of Notice	. Report, or O	ther Data			on manaman	egano o	A CONTRACTOR		
11 Check Appropriate Box to Indecate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT RE						PORT O	F:					
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL W	ORK]	AL	TER CASING				
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE	DRILLING OPNS.	. [PL	UG AND ABA	٧.			
PULL OR ALTER CASING			CASING TES	F AND CMT JOB	•	1				_		
OTHER:			OTHER:	FRAC/ACE	OZ/PERF					X		
										-		
12. Describe Proposed or Completed		nent details, and gi	ve pertinent da	tes, including			<u>'</u>					
usticated date of starting any propi	beed work) SEE HULE 1103.											
MODE CTART	ED 07/40/04 10/51	A.m. 1444						_				
WORK START	ED 07/12/94. MIRU,	ND WH, NU	ROP. SM	AB. SET RI	BP AT 35	01'. LO	AD HOL	E.				

W/2% KCL. RUN CBL/CET/GR/CCL LOG FROM 3500'-2000'. ACDZ W/150 GALS 15% NEFE HCL. SWAB. FRAC PERFS W/41,250 GALS 50Q CO2 LINEAR GEL & 152,000 LBS 12/20 BRADY SD. FLOWBACK. PERF F/3332'-3060'. ACDZ PERFS W/3.5 BBLS HCL. SWAB. FRAC PERFS

W/41,250 GALS 50Q CO2 LINEAR GEL AND 152,000 LBS 12/20 BRADY SD. FLOWBACK.

CLEAN OUT. ND BOP, NU WH. TURN WELL OVER TO PRODUCTION 07/22/94.

I hereby certify that the information about SIGNITURE	to be transfer compliate to the best of my know	viedge and belief. TECH. ASSISTANT	DATE:	08/04/94
TYPE OR PRINT NAME	WENDI KINGSTON		TELEPHONE NO.	(915)687-7436
APPROVED BY	TITLE	ty the second to the second second to the second	CON A	AUG 08 1994
CONDITIONS OF APPROVAL, IF ANY:			•	