STATE OF NEW ME IRGY AND MINERALS DE	
47 COPIES ACCEIVED	

	Ī	
DISTRIBUTION		· -
SANTA FE	Ì	
FILE		$\Box$
U.S.G.S.		
LAND OFFICE		
OPERATOR	+	;

DISTRIBUTION	12 SOUSER VALION DIVISION	
SANTA FE	P. O. BOX 2088	Form C-103
FILE	SANTA FE, NEW MEXICO 87501	Revised 10-1-78
U.S.G.S.		
LAND OFFICE		5a. Indicate Type of Lease
OPERATOR		State XX Fee
3. 2		5. State Oll & Gas Lease No.
SUNDRY NOTICE USE THIS FOR MORE PROPOSALS TO DI USE "APPLICATION FOR PERM	ES AND REPORTS ON WELLS  RILL ON TO OCCIPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  MIT - " FORM C-101) FOR SUCH PROPOSALS.)	
211	TOOK PROPOSACS.)	
WELL OTHER-	Injector	7. Unit Agreement Name
me at Operator	111111111111111111111111111111111111111	Eunice Monument South Un
Chevron U.S.A. Inc.		8. Farm or Lease Name
dress of Operator		
P.O. Box 670 Hobbs, NM	88240	9. Well No. 297
cation of Well		
VMIT LETTER # 1980	EET FROM THE North LINE AND 660	10. Field and Pool, or Wildcat
		Eunice Monument GB/SA
THE East INC. Section 8	TOWNSHIP 21S RANGE 36E	
LINE, SECTION	TOWNSHIP RANGE	_ NMPM. (
	5 Flavour (Clarity of the Company)	
. <i>(111111111111111111111111111111111111</i>	5. Elevation (Show whether DF, RT, GR, etc.)	12. County
TI	3592	Lea ()
Check Appropriat	te Box To Indicate Nature of Notice, Report	Col D
NOTICE OF INTENTION	To:	or Other Data
	SUBSEQ	QUENT REPORT OF:
ORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	~
PORARILY ASANDON	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
OR ALTER CASING	COMMENCE ORILLING OPHS.	PLUG AND ABANDONMENT
_	CHANGE PLANS CASING TEST AND CEMENT JOB	
Deepen,	OTHER	
THER run liner, perf, acidize	X	
)escribe Brossed of Completed Completed		
pork) SEE RULE 1103.	early state all pertinent details, and give pertinent dates, inc	ing estimated date of starting any proposed
•		s and once of starting any proposes
It is proposed to deepen f	/3960 to 3970. Run 4 1/2" liner, log	CD / CGT / CDT
Perf the 4 1/2" liner u/ 2	1/9" or 2 2//! or - 1 gpg (100 1	, w/ GR/CCL/CBL.
at 2717 2722 2720 27/6 /B	1/8" or 2 3/4" guns, 1 SPF w/ 180 de	gree phasing
at 3/1/=3/22, 3/30=3/46 (Z)	one 1), 3750-3754, 3782-3792, 3800-38	308, 3815-3824 (Zone 2),
3030-3030, 383/-3864 (Zone	3), 3886-3896, 3910-3920 (Zone 4), 3	3934-3952 (Zona 5)
103 notes. Acidize w/ 5000	O gallons 15% NEFE HCL. Swab back. T	est, turn over to
production department.		3 2 3 2 3 2 3 2 3 2 3 2 3 2 3 2 3 2 3 2
ereby certify that the information above is true	and complete to the best of my knowledge and belief.	
-	which the best of my knowledge and belief.	
M. E. apin		
man	Tire: Staff Drilling Engineer	August 18, 1988
ORIGINAL SIGNED BY JERRY SE		13-
DISTRICT I SUPERVISOR	VIOIA	AUG 0 PV2
(D 17		Fig. (2)

RECEIVE,

AUG 1 9 1996

OCH HODES OFFICE