

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
HOBBS, NEW MEXICO 88240

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME Eunice Monument South Unit
2. NAME OF OPERATOR Chevron U.S.A. Inc.	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR P.O. Box 670, Hobbs, New Mexico 88240	9. WELL NO. 321
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit K, 1980' FSL & 1980' FWL	10. FIELD AND POOL, OR WILDCAT Eunice Monument G/SA
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 9, T21S, R36E
15. ELEVATIONS (Show whether DP, ST, GR, etc.) 3577' GL	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) Deepen Add Perforations Acidize <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Clean out to TD @ 3902'. Deepen from 3902' to 3958'. Log well. Add perforations as logs indicate. Acidize as necessary. Return to production.

18. I hereby certify that the foregoing is true and correct

SIGNED M. E. Abbin

TITLE Staff Drilling Engineer

DATE 21-23-1986

(This space for Federal or State office use)

APPROVED BY Orig. Sgd. Linda J. Medall
CONDITIONS OF APPROVAL As Manager

TITLE _____

DATE 1-12-87

*See Instructions on Reverse Side