

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions
reverse side)

TE
re

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS 100 88240

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR CONOCO INC.	8. FARM OR LEASE NAME Meyer B-9
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240	9. WELL NO. 2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit F	10. FIELD AND POOL, OR WILDCAT Eumont Queen Gas
14. PERMIT NO. 1980' FNL & 1980' FWL 30-025-04571	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 9-215-36E
15. ELEVATIONS (Show whether OF, RT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☐
(Other)			

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☒
(Other) Convert to useable W.B. (safety)			

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- ① MIRU on 8-5-86. POOH w/pump & rods. Couldn't get pkr out of hole
- ② Chemically cut tbg @ 3341'. Caught fish @ 3341', POOH w/fish. Top of fish @ 3643'. Caught fish & pkr worked loose. POOH w/tbg & pkr.
- ③ Set CIBP @ 3725'. Set RBP @ 3615'. Dumped 25 sxs sand on top. Set pkr @ 3455'. Broke down lower Eumont perfs w/ 220 bbls gelled 10lb brine. Communicated w/ upper Eumont, broke down entire zone w/ 360 bbls gelled 10lb brine. Reset pkr @ 3270', flush w/ 70 bbls fresh wtr.
- ④ Set cmt ret @ 3345'. Sqz'd Eumont perfs w/ 300 sxs class "C" w/ 2% Cal₂ Tag TOC @ 3340'. Drilled out cmt & junk to 3455'. Tested sqz to 500psi, held. Drill from 3455'-3600'. Tested sqz to 500psi, held. Clean out to RBP. POOH w/RBP. Drill out liner from 3630' to 3699'. Spot 25 sxs Cal-Seal from 3630'-3704'. Tag cmt @ 3654'. Drill out to 3674'.
- ⑤ G1H w/ whip stock @ 3661'. Mill w/ starting mill to 3663'. Mill w/ hole opener mill to 3671'. Drill from 3671'-3870'. Circ. hole clean. Tested csq to 500 psi f. 15 min & held OK. This well will be turned over to Chevron as a Eunice Monument so. well. Rig down on 8/25

18. I hereby certify that the foregoing is true and correct

SIGNED <i>[Signature]</i>	TITLE Administrative Supervisor	DATE 9-18-86
---------------------------	---------------------------------	--------------

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:
ACCEPTED FOR RECORD

SEP 26 1986

*See Instructions on Reverse Side