

SE 5047 - disconnected (Eumont) Conoco-meyer B-9#2

Inj. (DB) R 7766

superseded by R-9430

NSP-287-160 ac. E/2 N/2 Sec. 9 DC-321