Submit 3 Copies To Appropriate District Office State of Nev Energy Minerals and	w Mexico			HOT	m C-10	
	Matural Dagouroog				1 05 10	
District I	ivaturai Resources	WELL AD		evised Marc	n 25, 19	
1625 N. French Dr., Hobbs, NM 87240		WELL API		ı		
District II 811 South First, Artesia, NM 87210 OIL CONSERVAT			30-025-04574 5. Indicate Type of Lease			
District III 2040 South	2040 South Pacheco					
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, N District IV	M 87505	<u> </u>		FEE L		
2040 South Pacheco, Santa Fe, NM 87505			6. State Oil & Gas Lease No.			
SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well: Gas Well Other INJECTOR		7. Lease Name or Unit Agreement Name:				
		EUNICE MONUMENT SOUTH UNIT				
Name of Operator		8. Well No.	8. Well No.			
Chevron U.S.A. Inc.	<u></u>	322	<u>. </u>			
3. Address of Operator		9. Pool nan	ne or Wildcat			
P.O. Box 1150 Midland, TX 79702		EUNICE MON	UMENT; GRAY	BURG-SAN	ANDRES	
Unit Letter L : 1980 feet from the			eet from the_		lin	
Section 9 Township 21		NMPM ata.)	Coi	ınty	LEA	
10. Elevation (Show who	ether DR, RKB, RT, GR, 3591'	etc.)				
11. Check Appropriate Box to Ind		e Report or	Other Data	ALM MIN. 1		
		-				
NOTICE OF INTENTION TO:		JBSEQUEN [*]				
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK	(, , ,)	X AL	TERING CA	ASING	
TEMPORARILY ABANDON		LLING OPNS.		UG AND	:NIT	
PULL OR ALTER CASING	CASING TEST AN	1Ď		ANDONME	I.W.I	
OUM LETON	I CEMENT JOD					
OTHER:	OTHER:	I give pertinent	dates, includi	ng estimate	ed date	
	OTHER: e all pertinent details, and altiple Completions: Atta N. DUMPED 2200# SAM PPD 50 SX CMT; SQZD O SD TO 3970'; CIRC O	o; TAGGED @ 3 31 SX IN FOR	gram of prop 849'. M.			
OTHER: 12. Describe Proposed or Completed Operations (Clearly state of starting any proposed work). SEE RULE 1103. For Mulor recompilation. POH W/INJ EQPT. WASHED 3740'-3971'; CIRC CLEAN SPOTTED 100# SAND. POLYMER SQZD 3744'-3844'. DO CMT TO 3850'; CIRC CLEAN. TSID SQZ. WASHED INJ PKR TO 3700'. RAN MIT. RETURNED WELL TO I WORK PERFORMED 7/27/00 - 8/8/00 Thereby certify that the information above is true and complete to the business of the same of the sam	OTHER: e all pertinent details, and altiple Completions: Attain. DUMPED 2200# SAM PPD 50 SX CMT; SQZD D SD TO 3970'; CIRC ONJECTION. Dest of my knowledge and be a set of my knowledge.	ch wellbore dia 7: TAGGED @ 3 31 SX IN FOR TLEAN. RIH W	gram of prop 849'. M.	osed comp	/oo	
OTHER: 12. Describe Proposed or Completed Operations (Clearly state of starting any proposed work). SEE RULE 1103. For Mulor recompilation. POH W/INJ EQPT. WASHED 3740'-3971'; CIRC CLEAN SPOTTED 100# SAND. POLYMER SQZD 3744'-3844'. DO CMT TO 3850'; CIRC CLEAN. TSID SQZ. WASHED INJ PKR TO 3700'. RAN MIT. RETURNED WELL TO I WORK PERFORMED 7/27/00 - 8/8/00 Thereby certify that the information above is true and complete to the business of the same of the sam	OTHER: e all pertinent details, and altiple Completions: Attain. DUMPED 2200# SANI PPD 50 SX CMT; SQZD D SD TO 3970'; CIRC ONJECTION. Dest of my knowledge and beautiful to the complete of	ch wellbore dia 7: TAGGED @ 3 31 SX IN FOR TLEAN. RIH W	gram of prop 849'. M. /TBG &	osed comp	detion	
OTHER: 12. Describe Proposed or Completed Operations (Clearly state of starting any proposed work). SEE RULE 1103. For Mu or recompilation. POH W/INJ EQPT. WASHED 3740'-3971'; CIRC CLEAN SPOTTED 100# SAND. POLYMER SQZD 3744'-3844'. DO CMT TO 3850'; CIRC CLEAN. TSID SQZ. WASHED INJ PKR TO 3700'. RAN MIT. RETURNED WELL TO I	OTHER: e all pertinent details, and altiple Completions: Attain. DUMPED 2200# SAM PPD 50 SX CMT; SQZD D SD TO 3970'; CIRC ONJECTION. Dest of my knowledge and be a set of my knowledge.	C); TAGGED @ 3 31 SX IN FOR LEAN. RIH W	gram of prop 849'. M. /TBG &	osed comp	/oo	

