Submit 3 Copies to Appropriate

State of New Mexico

District Office	Energy, Minerals and Natural Resources Department			Form C-103 Revised 1-1-89	
DISTRICT I P.O. Box 1980, Hobbs NM 88241-1980	OIL CONSERVATI			20)	
DISTRICT II	P.O. Box 2088		WELL API NO		
P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87504-2088		5. Indicate Typ	30-025-04581	
DISTRICT III			STATE	FEE X	
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & (Gas Lease No.	
SUNDRY NOTI	CES AND REPORTS ON WE	LLS	<i>VIIIIIIIII</i>		7777777
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7 January		
(FORM C-101) FOR SUCH PROPOSALS)			/. Lease Name	or Unit Agreement Name	
I. Type of Well:		FUNICE MONIL	IMENT COUTH HAVE		
OIL GAS WELL	OTHER INC	EUNICE MONUMENT SOUTH UNIT			
2. Name of Operator			8. Well No.		
Chevron U.S.A. Inc. 3. Address of Operator		279			
P.O. Box 1150, Midland	. TX 79702	9. Pool name or	Wildcat		
4. Well Location			LEUNICE MUNU	MENT; GRAYBURG-SAN	ANDRES
Unit Letter B : 330	Feet From The NORTH	Line and231	10 Feet Fro	om The EAST	Line
Section 9	Township 21S	tange 36E			
		Range 36E her DF, RKB, RT, GR, etc	NMPM .)	LEA	County
11. Chook Ana		3590 <i>°</i>			
Спеск Арр	propriate Box to Indicate	Nature of Notice,	Report, or	Other Data	
NOTICE OF IN	TENTION TO:	SUB	SEQUENT	REPORT OF:)
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK			_
TEMPORARILY ABANDON	CHANGE PLANS	1		ALTERING CASING	Ļ.
PULL OR ALTER CASING	CHANGE PLANS [_]	COMMENCE DRILLING		PLUG AND ABANDONA	MENT _
_		CASING TEST AND CEN	MENT JOB		
OTHER:		OTHER:ACZD,	SQZD		X
 Describe Proposed or Completed Opera work) SEE RULE 1103. 	tions (Clearly state all pertinent de	ails and sive	1 1 1		
work) SEE RULE 1103.	various y some an per unent uer	aus, and give pertinent date	s, including estim	ated date of starting any	proposed
POH W/INJ EQPT. PIC	KLED TBG @ 3762' W/500 GA	IS 154 NEUCI ACTO	DEDEC 4 4		
POH W/INJ EQPT. PICKLED TBG @ 3762' W/500 GALS 15% NEHCL. ACZD PERFS & OH W/1500 GALS 15% RS II. PLUGGED BACK W/SAND TO 3763'. SET CIBP @ 3762'. SET CICR @ 3619'. PPD 200 SX CL "C". SOZD 172 SX IN FORM. DO CICR & CMT TO 3763'. PO CICR & 3619'.					
"C", SQZD 172 SX IN FORM. DO CICR & CMT TO 3762'. DO CIBP & CMT TO 3777'. WASHED SD TO 3875', CIRC HOLE CLEAN. RIH W/INJ TBG & PKR TO 3633'. RETURNED WELL TO INJECTION.					
3875, CIRC HOLE CLE	W. RIH W/INJ TBG & PKR	TO 3633'. RETURNED	WELL TO INJ	ECTION.	
WORK PERFORMED 11/25/97 - 12/9/97					
	22/3/3/				
•	V				
I hereby certify that the information above is true	and complete to the best of my knowledge	and belief.			
SIGNATURE OK, KIPLLY		E TECHNICAL ASSISTA	NT	1/10/6	00
TYPE OR PRINT NAME J. K. RIPLE			""	DATE1/19/9	<u>18</u>
			1	ELEPHONE NO. (915)687	7-7148
(This space for State Use) ORIGINAL S CORE TO	175E000 586 F0A375		·		=
					
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITL	E		DATE	· • • • • • • • • • • • • • • • • • • •
· · · · · · · · ·					