Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office		<u>-</u>	Keviseu 1.1.0)
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATI		WELL API NO.
	P.O. Box 2088		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87504-2088		30-025-04600
			5. Indicate Type of Lease STATE FEE XX
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.
			o. State on the state from
SUNDRY NOTI	CES AND REPORTS ON W	ELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"		7. Lease Name or Unit Agreement Name	
	1VOIH. USE "APPLICATION FOR F -101) FOR SUCH PROPOSALS.)	ERMIT"	
1. Type of Well:	TOTAL CONTENTS CONCO.		- EUNICE MONUMENT
OIL GAS WELL X			SOUTH UNIT
2. Name of Operator	OTHER		
CHEVRON U.S.A. INC.			8. Well No. 315
3. Address of Operator			
P.O. BOX 1150 MIDLAND,	TY 79702 ATTN. P.P. !	MATTHEMS	9. Pool name or Wildcat EUNICE MONUMENT AB-SA
4. Well Location	1X 79702 ATTR. F.K. I	TATTIEWS	LONICE MONOMENT ALS A/T
Unit Letter I : 1980	Fact From The SOUTH	Line and 660	Feet From The EAST Line
	rea From the	Line and	Feet From The Line
Section 10	Township 21S	Range 36E	NMPM LEA County
	10. Elevation (Show whether	er DF, RKB, RT, GR, etc.)	WIND COUNTY
	3699		<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>
11. Check A	Appropriate Box to Indicate	Nature of Notice, Re	eport, or Other Data
NOTICE OF INT			SEQUENT REPORT OF:
		000	DEGOENT REPORT OF
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CE	MENT JOB
OTHER: LOG, PERF, ACDZ	X	OTHER:	
12. Describe Proposed or Completed Operation	ions (Clearly state all persinent details		J
work) SEE RULE 1103.	ous (clearly state ou personers destats, t	ina give periineni aaies, inclua	ung estimatea date of starting any proposed
IT IC DRODOCED TO.			
IT IS PROPOSED TO:			
LOG WELL			
PERFORATE ZONE 1 OF THE	F GDAVRIIRG DAV AT 372	1_36	
PERIORATE ZONE I OF THE	2 GRATBORG TAT AT 372	T-30•	
ACIDIZE PERFS AND OPEN	HOLE 3925-3724.		
RETURN TO PRODUCTION.			

I hereby cerufy that the information bove is true and complete to the best of my	Enowledge and belief. DRILLING ENGINEER.	B-5-91
TYPEOR PRINT NAME JOE CARTER		TELEPHONE NO 687-7812
(This space for State Use)		
APPROVED BY	тпъ	DATE