

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I

P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.
Santa Fe, NM 87505

| |
|---|
| WELL API NO. 30-025-04602 |
| 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. |
| 7. Lease Name or Unit Agreement Name EUNICE MONUMENT SOUTH UNIT |
| 8. Well No. 274 |
| 9. Pool name or Wildcat EUNICE MONUMENT; GRAYBURG-SAN ANDRES |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Chevron U.S.A. Inc.

3. Address of Operator
P.O. Box 1150, Midland, TX 79702

4. Well Location
Unit Letter A : 660 Feet From The NORTH Line and 660 Feet From The EAST Line
Section 10 Township 21S Range 36E NMPM LEA County

| | |
|---|---|
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data | |
| NOTICE OF INTENTION TO: | SUBSEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK <input type="checkbox"/> | REMEDIAL WORK <input checked="" type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> |
| OTHER: <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
| | OTHER: <input type="checkbox"/> |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH W/PROD EQPT. TAGGED TD @ 3891'. SPOTTED 15 SX CMT @ 3890', TAGGED @ 3885'. SPOTTED 15 SX CMT @ 3885', TAGGED @ 3881'. SPOTTED 2 SX SAND ON PLUG, TAGGED @ 3878'. WASH OH & PERFS W/PERF CLEAN TOOL 3860'-3700' W/1500 GALS RS II. RIH W/TBG, PUMP & RODS. RETURNED WELL TO PRODUCTION.

WORK PERFORMED 2/2/98 - 2/6/98

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. K. Ripley TITLE _____ DATE _____

TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

APPROVED BY CHRIS WILLIAMS
SUPERVISOR

CONDITIONS OF APPROVAL, IF ANY: _____ TITLE _____ DATE _____