

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III


1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) 30-025-04614	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. 2616	
7. Lease Name or Unit Agreement Name EUNICE MONUMENT SOUTH UNIT	
8. Well No. 350	
9. Pool name or Wildcat EUNICE MONUMENT	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3476	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER INJECTOR <input type="checkbox"/>	
2. Name of Operator CHEVRON U.S.A. INC.	
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: WENDI KINGSTON	
4. Well Location Unit Letter O : 330 Feet From The SOUTH Line and 990 Feet From The EAST Line Section 11 Township T21S Range R36E NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3476	

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input checked="" type="checkbox"/> ALTER CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABAN. <input type="checkbox"/> CASING TEST AND CMT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. MIRU, ACDZ W/4000 GALS ACID. RDMO, TURN WELL OVER TO PRODUCTION 07/28/95.	
--	--

I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE 	TITLE TECH. ASSISTANT
DATE: 08/18/95	
TYPE OR PRINT NAME WENDI KINGSTON	
TELEPHONE NO. (915)687-7826	
APPROVED BY	TITLE
CONDITIONS OF APPROVAL, IF ANY:	
DATE AUG 28 1995	

RECEIVED

AUG 21 1905

OLD FARM
HISSE

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240DISTRICT II
P.O. Drawer DD, Artesia, NM 88210DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☐FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐GAS
WELL ☐

OTHER - WIW

2. Name of Operator

Chevron U.S.A., Inc.

3. Address of Operator

P.O. Box 670, Hobbs, New Mexico 88240

7. Lease Name or Unit Agreement Name

Eunice Monument South Unit

8. Well No.

350 ~~WEL~~

9. Pool name or Wildcat

Eunice Monument Grayburg S/A

4. Well Location

Unit Letter P : 330 Feet From The South Line and 990 Feet From The East LineSection 11Township 21SRange 36E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐CHANGE PLANS ☐PULL OR ALTER CASING ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐PLUG AND ABANDONMENT ☐CASING TEST AND CEMENT JOB ☐OTHER: Cellar Inspection ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Dug up cellar and repiped the casing valve to surface.

Inspected by OCD representative 1-5-89.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. L. Morrill TITLE NM Area Prod. Supt. DATE 1-30-89TYPE OR PRINT NAME C. L. MorrillTELEPHONE NO. 505-393-4121

(This space for State Use)

APPROVED BY R. A. Sadler TITLE OIL & GAS INSPECTOR DATE FEB 02 1989

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

FEB 1 1989

OCD
HOBBS OFFICE

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER ☒ **Injector**

Name of Operator
Chevron U.S.A. Inc.

Address of Operator
P.O. Box 670, Hobbs, NM 88240

Location of Well
UNIT LETTER **P**, **330** FEET FROM THE **South** LINE AND **990** FEET FROM THE **East** LINE, SECTION **11** TOWNSHIP **21S** RANGE **36E** NMPM.

7. Unit Agreement Name
Eunice Monument South

8. Farm or Lease Name
Eunice Monument G/SA

9. Well No.
350

10. Field and Pool, or Wildcat
Eunice Monument G/SA

11. Elevation (Show whether DF, RT, GR, etc.)
3484

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

REFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
REPAIR OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☒ **run liner, log, perf, conv to inj.**

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 7145 PB: 3922

POOH w/ production equipment. Change out wellhead. NU BOP and test to 600psi. Cleanout fill to 3925. Run 4" liner to 3549', Cement w/300sx Class C. bump plug, circ 40sx to surface. Cleanout to 3922. Circulate hole clean, test casing to 1500psi, f/30min. Run GR,CCL, f/3916 to 2900'. Perf 3722-32, 3765-72, 3790-3805, 3824-26, 3876-84, 3892-3906, 3910-3916 (72 holes) 1 JHPF 2 7/8" guns 180° phase. RU Halliburton, spot 150gallons 15% NEFE HCL across perfs, Swab., TIH w/ 2 3/8" IPC tbg to 3677, ND BOP, NUWH, test to 600psi, for 30 min. ok. Work performed 10-4-87 through 10-8-87.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

by M. E. Ahim TITLE Staff Drilling Engineer DATE Oct. 9, 1987

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

COPIES BY DISTRICT I SUPERVISOR TITLE DATE OCT 14 1987

ADDITIONS OF APPROVAL, IF ANY: