

COPIES RECEIVED	
DISTRIBUTION	
NT FE	
LE	
S.G.S.	
AND OFFICE	
PERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
R. B. McQuatters Unit	
9. Well No.	
1	
10. Field and Loc. or Wildcat	
Eumont Gas	
11. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL ☐ WELL ☐ GAS ☒ WELL ☒ OTHER ☐

Name of Operator
Dalport Oil Corporation

Address of Operator
3471 First National Bank Bldg., Dallas, Texas 75202

Location of Well
UNIT LETTER E 1650 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 12 TOWNSHIP 21S RANGE 36E N.M.P.M.

15. Elevation (Show whether OF, RT, GR, etc.)
3523 G.L.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

REPAIR REMEDIAL WORK <input type="checkbox"/>	PLUS AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUS AND ABANDONMENT <input checked="" type="checkbox"/>
REPAIR OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work, SEE RULE 1103.)

Well Data: T.D. 3391 8 5/8 Set @ 1323" W/250 SX in 11" Hole
5 1/2" Set @ 3391 W/200 SX. 150 Sx. 150 Sx. Cmt. Plug
Set From T.D. to 2305" Inside 5 1/2" Cug.

Well Plugged As Follows:

1. Shot 5 1/2" Cug. @ 1845', 1810', 1749', Shot & Recovered Cug. from 1650'
2. Ran Tbg. & Set a 35' Sx. Cement Plug from 1643' to 1520'
3. Ran Tbg. & Set a 50' Sx Cement Plug from 1364' to 1220' @ 8 5/8 Shoe
4. Set 10 Sack Cement Plug @ Surface & Installed Dry Hole Marker

Hole was circulated W/ and all plugs set W/ Gelled Mud.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Gene Milford</u>	TITLE <u>Agent</u>	DATE <u>4/12/76</u>
PROVED BY <u>Gene Milford</u>	TITLE <u></u>	DATE <u></u>

CONDITIONS OF APPROVAL, IF ANY: