Submit 3 Copies To Appropriate Distri Office District I		State of New Mexico F -gy, Minerals and Natural Resources		Form C-10. Revised March 25, 199	
1625 N. French Dr., Hobbs, NM 87240 District II				WELL API NO.	
811 South First, Artesia, NM 87210		OIL CONSERVATION DIVISION		30-025-04631 5. Indicate Type of Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	_	2040 South Pacheco			
District IV	Sunta i C	Santa Fe, NM 87505		K FEE	
2040 South Pacheco, Santa Fe, NM 875	505		6. State Oil & Ga	s Lease No.	
DIFFERENT RESERVOIR. USE "AP PROPOSALS.)	OTICES AND REPORTS CROPOSALS TO DRILL OR TO DEPLICATION FOR PERMIT" (FO	FEPEN OR PLUG BACK TO A	7. Lease Name or	Unit Agreement Name:	
	I X Gas Weli Other			EUNICE MONUMENT SOUTH UNIT	
2. Name of Operator			8. Well No.		
hevron U.S.A. Inc.			389		
3. Address of Operator P.O. Box 1150 Midland, TX 79702			9. Pool name or Wildcat		
4. Well Location	. 79702		EUNICE MONUMENT	CRAYBURG-SAN ANDRES	
Unit Letter <u>E</u> :	1980 feet from the	NORTH line and	660 feet fro	m the WEST line	
Section 14	Township 2	21s Range 36E	NMPM	County Tran	
		hether DR, RKB, RT, GR, et		County IFA	
A. 4					
11. Chec	k Appropriate Box to In	dicate Nature of Notice,	Report, or Other	Data	
	NTENTION TO:	SUB	SEQUENT REP	PORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON			ALTERING CASING	
EMPORARILY ABANDON	X CHANGE PLANS	COMMENCE DRILLI	ING OPNS.	PLUG AND [ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB		ADAMOONMENT	
OTHER:		OTHER:		ſ	
12. Describe Proposed or Compl of starting any proposed work or recompilation.CHEVRON PROPOSES TO TA	k). SEE RULE 1103. For M FER THE ATTACHED PROCED	ultiple Completions: Attach	ve pertinent dates, ir wellbore diagram of	cluding estimated date proposed completion	
nereby certify that the information abo	ove is true and complete to the	est of my knowledge and belief.			
gnature J. K. K.	sley	TITLE REGULATORY O.A.	D	ATE3/11/02	
pe or print name J. K. RIPLEY	V		Telephon	e No. (017) 607 7116	
his space for State use)			Telephon	MAR 1 9 2002	
PPROVED BY	ORIGINAL!	SHATED BY	DA	TE	
onditions of approval, if any:	GARY W. V	VINK REPRESENTATIVE II/STAFF	MANAN		

EMSU # 389 API # 30-025-04631 1980' FNL & 660' FWL S14, T21S, R36E, & Unit E Eunice Monument South Unit Lea County, New Mexico

PROCEDURE TO TEMPORARILY ABANDON WELL:

Notify OCD/BLM 24 hrs prior to work commencing.

- 1. Verify anchors have been set & tested.
- 2. MIRU PU. ND WH. NU BOP.
- 3. Pull rods, pump and tubing.
- 3. TIH w/3-1/8" bit, csg scraper, & WS. Make bit trip to 3750'. POH.
- 4. Set CIBP @ 3725'. Dump 3 sx Class 'C' cmt on CIBP.
- 5. TIH w/WS to TOC. Circulate csg w/corrosion inhibited pkr fluid. TOH.
- 6. Perform MIT (500 PSI for 30 min.).
- 7. ND BOP. NU WH. RD PU.
- 8. Clean and clear location.

K. Hickey 687-7260

Chevron

WELL DATA SHEET

