

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-04648
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator Chevron USA, Inc.		6. State Oil & Gas Lease No.
3. Address of Operator 15 Smith Rd. Midland, Tx 79705		7. Lease Name or Unit Agreement Name Euncie Monument South Unit
4. Well Location Unit Letter P : 660 feet from the South line and 660 feet from the East line Section 15 Township 21-S Range 36-E NMPM County Lea		8. Section 428
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Field Name or Well Name Eunice Monument Grayburg S.A.

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒


CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. RIH Tag CIBP @ 3664'(Grayburg-Queen) Mix & Pump 30sx plug fr/3664' to 3400' Tag @ 3390'
2. Displace hole w/MLF, 9.5# Brine w/25 # Gel p/BBL
3. Spot 25sx plug fr/2600' to 2400' (B-salt)
4. Spot 35sx plug fr/1500' to 1200'(7 5/8" shoe, T-salt) Tag @ 1184'
5. Circ cmt fr/300' to surf w/35sx (10 3/4" shoe to surf) Tag @ surf
6. Install dry hole marker 8-14-02

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE **MANAGER**

DATE **8-14-02**

Type or print name

Jimmy BAGLEY / SUNSET

Telephone No. **915 520-8766**

(This space for State use)

APPROVED BY

TITLE

DATE

Conditions of approval, if any

GARY W. WINK

CC FIELD REPRESENTATIVE II/STAFF MANAGER

FEB - 6 2003

RECEIVED
JAN 10 1960
U.S. DEPARTMENT OF AGRICULTURE
WASHINGTON, D.C.