

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-85

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-1537
7. Unit Agreement Name
8. Farm or Lease Name state D
9. Well No. 12
10. Field and Pool, or Wildcat Eumont Queen Gas
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator CONOCO INC.
3. Address of Operator P. O. Box 460, Hobbs, N.M. 88240
4. Location of Well UNIT LETTER P 660 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 15 TOWNSHIP 21S RANGE 36E N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER sqz Eumont perms & clean out to TD <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

- ① MIRU on 10/18/85. Set bridge plug @ 3660' & pkr @ 3390'. Break down perms from 3494'-3648' w/ 150 bbls 10# brine.
- ② POOH w/ bridge plug & pkr and set cmt retainer @ 3450'. Pmp'd 100 sxs class "c" w/ 2% CaCl₂. Reverse out cmt. WOC. Drilled out cmt retainer @ 3450' and cmt to 3658'. Press. test sqz to 500 psi, held OK.
- ③ Clean out to 3671'. Couldn't get through bridge plug. Milled up bridge plug and pulled out of hole.
- ④ Drilled through cmt retainers @ 3780', 3800', 3810', & 3885'. Clean out to TD @ 3908'. Circ. hole clean.
- ⑤ Rig down on 10/29/85.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

Kevin L. Vogel

TITLE **Administrative Supervisor**

DATE

1-3-86

ORIGINAL SIGNED BY **JERRY SEXTON**

DISTRICT I SUPERVISOR

APPROVED BY

TITLE

7M (Halt)

DATE

JAN 7 - 1986

11 Macdon-Hobbs(?) File

RECEIVED
JAN 6 - 1986
O.C.D.
HOBBS OFFICE