

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
Chevron U.S.A. Inc.

Address of Operator
P.O. Box 670 Hobbs, NM 88240

Location of Well

UNIT LETTER K 3300 FEET FROM THE North LINE AND 1980 FEET FROM
THE West LINE, SECTION 6 TOWNSHIP 21S RANGE 36E NMPM.

7. Unit Agreement Name

Eunice Monument South Unit

8. Farm or Lease Name

9. Well No.

218

10. Field and Pool, or Wildcat

Eunice Monument GB/SA

15. Elevation (Show whether DF, RT, GR, etc.)

3558

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

FORM REMEDIAL WORK ☐
PERMANENTLY ABANDON ☐
OR ALTER CASING ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOBS ☐

OTHER run liner, perf. ☒

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work performed 12-20-88 12-24-88

POOH w/rods, tag btm at 3968'. Load ann, tst to 500psi, ok. PU 4 1/2" liner, TIH to 3968'. Batch mix 80sx C1 C. Pmp 50bbls wtr, 20bbls cmt slurry, displace w/FW. POOH, chg rams in BOP, WOC 24 hrs. TIH, tag TOL at 3446', no cmt on TOL. TIH, tag cmt at 3924'. CO cmt to 3928'. Circulate clean. RIH w/ CBL-GR-CCL and tie into comp density log 9-21-88. Log f/3938' to 3250'. Perf 3908-3912, 3899-3902, 3870-3878, 3854-3860 at 1 JHPF, 25 holes. Spot acid to EOT, and acidize w/750 gallons 15% NEFE HCL. Swab. Run production equipment. ND BOP, NUWH, Run rods, space and hang on. Load tbg w/ FW and tst 600psi, ok. Turn over to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

L. L. Elmae

TITLE Technical Assistant

DATE January 5, 1989

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

DATE

TITLE

DATE

REMARKS OF APPROVAL, IF ANY:

JAN 09 1989

RECEIVED

JAN 9 1989

U.S. AIR FORCE

RECEIVED

NOV 1988