

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL APL NO. 30-025-04660
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Well Agreement Name Eunice Monument South Unit
8. Well No. 381
9. Production Well Eunice Monument Grayburg, S.A.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Chevron USA, Inc.	
3. Address of Operator 15 Smith Rd. Midland, Tx 79705	
4. Well Location Unit Letter <u>E</u> : <u>1980</u> feet from the <u>North</u> line and <u>660</u> feet from the <u>West</u> line Section <u>16</u> Township <u>21-S</u> Range <u>36-E</u> NMPM County <u>Lea</u>	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.
1. RIH Tag TOC 3524' Mix & Pump 60sx plug fr/3524' to 3200'(4" Liner Queen) Tag @ 3191'
 2. Displace hole w/MLF. 9.5# Brine w/25# Gel p/BBL
 3. Mix & Pump 40sx plug fr/2600' to 2400' (B-salt)
 4. Mix & Pump 60sx plug fr/1725' to 1400' (9" shoe, T-salt) Tag @ 1410' ok w/OCD
 5. Mix & pump 25sx plug fr/400' to 300' (fresh water)
 6. Circ cmt fr/60' to surf w/12sx. Install dry hole marker 7-25-02

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

JUL 2002
FILED
Hobbs
OCD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE MANAGER/SUNSET WELL DATE 7-29-02

Type or print name Jimmy BAGLEY Telephone No. 915 520-8756
(This space for State use)

APPROVED BY [Signature] TITLE _____ DATE FEB - 7 2003

Conditions of approval, if any:
GARY W. WINK
OC FIELD REPRESENTATIVE II/STAFF MANAGER

GWW

SCS

8