

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR CONOCO INC.	8. FARM OR LEASE NAME Lockhart A-18
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240	9. WELL NO. 3
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit K 1980' FSL & 1980' FWL	10. FIELD AND POOL, OR WILDCAT Eumont Queen Gas
14. PERMIT NO. 30-025-04672	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 18-215-36E
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☐
(Other) Convert to useable wellbore	☒		

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
(Other)	☐		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- ① MIRU. POOH w/ tbg. Run bit to BT0 (3740')
- ② Set pkr @ 3050'. Break down Eumont perms from 3168'-3729' w/ 690 bbls 10 ppg brine + 10lb/1000 gal guar gum. Release pkr @ 3050. POOH
- ③ Set retainer @ 3130'. Sgz Eumont perms from 3168'-3729' w/ 300 SKS Class "C" w/ 2% CaCl₂. Will not pump more than 18 bbls flush.
- ④ WOC 12 hrs. Drill up ret @ 3130' & cmt to 3290'. Test sgz to 500 psi, resgz if necessary.
- ⑤ Drill up cmt to 3766'. Test lower sgz to 500 psi, resgz if necessary
- ⑥ Set whipstock tool & starting mill on cmt top @ 3766'. Mill out window in 5 1/2" casing @ 3751'. Drill 4 3/4" hole to 4048'.
- ⑦ Circ. hole clean. Rig down.
- ⑧ This well will go into Chevron's Eunice Monument South Unit.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Administrative Supervisor

DATE 12-3-86

(This space for Bureau or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE 12-9-86

*See Instructions on Reverse Side

RECEIVED
DEC 1 9 10:45
OCD
HDBS OFFICE