		Budget Bureau 42-R358.2. Approval expires 12-81-52.		
	(SUBMIT IN TRIPLICATE) UNITED STATES EPARTMENT OF THE INT GEOLOGICAL SURVEY	Land Office Lass Cruces Lease No. 032099 (a) Lease No. 032099 (a) N. M. F. U. N. M. F. U. JUL 16 1951		
NOTICE OF INTENTION TO DRILL NOTICE OF INTENTION TO CHANGE PLAN NOTICE OF INTENTION TO TEST WATER NOTICE OF INTENTION TO RE-DRILL OR NOTICE OF INTENTION TO SHOOT OR AC NOTICE OF INTENTION TO PULL OR ALT NOTICE OF INTENTION TO ABANDON WE	NSSUBSEQUENT REPO SHUT-OFFSUBSEQUENT REPO REPAIR WELLSUBSEQUENT REPO CIDIZESUBSEQUENT REPO SUBSEQUENT REPO SUBSEQUENT REPO SUBSEQUENT REPO	ORT OF WATER SHUT-OFF		
(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)				
Lockhart A-18 No. 3	ilobbs, New	Maxico July 13, 19 51		
Well No3 is locat	ted	$\frac{1230}{W}$ ft. from $\begin{cases} E \mathbf{X} \\ W \end{cases}$ The of sec. 18		
9W/4 Sec. 18	21-5 36-B (Twp.) (Range)	N. M. P. K. (Meridian)		
(14 Sec. and Sec. No.)	(Twp.) (Range)	(Meridian)		
Bunice		Now Mexico		
(Field)	(County or Subdivision)	(State or 'Territory)		

The elevation of the derrick floor above sea level is _____3636ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The subject well has been shut in since Jan. 1, 1950, due to flooding out of the Grayburg formation, with a daily production of 50 bbls. water, no oil. As no additional remedial work can be accomplished to obtain additional oil production from the Grayburg, it is proposed to plugback and recomplete in the Mates formation.

In January 1948 a liner was installed from 3786 to 4048³ and comented with 60 sacks. The interval from 3892 to 4045³ was selectively perforated, tested, and each interval aqueezed with command. Completion was made thru perforations from 3860 to 3885⁴. As this interval is now flooded out, it is proposed to set a retainer above these perforations and squeeze below with 50 sacks coment; then selectively perforate and test the Yates formation from 3150 to 3300⁴ to recomplete as a gas well.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company	Continental 011 Company	
Address	Bax CC	1
	Hobbs, New Marcico	By G. L. Shaper
		TitleDistrict Superintendent

U. S. GOVERNMENT PRINTING OFFICE 16-8437-4



(2)

and the second second

்று அவரல்ல் நாகிற்கும் விண்டு பிருவில் பிருவில்ல் பிருவில் பிருதிய நிறையில் வில்லில் நான் பிருவில் பிரு மன்றுக்கு இல்லைய விடுகள் பிரியில் தின்றில் நின்றுகளில் கிறியில் பிரியில் பிருதிய நிலையில் நிறையில் நிறையில் உருக்கு நிறைலுக்கு இருந்தில் கிறில் முன்னோலில் பிரிவில் பிரியில் விக்கும் விலியில் பிரியில் பிரியில் பிரியில் உரிப்பது கிருக்கு பிருவில் பிரியில் தில்லுக்கு விடியில் தின்னையில் விக்கும் கிரியில் பிரியில் திலையில் திரையில் உரிப்பது கிருக்கு பிருக்கு பிரியில் தில்லுக்கு விடில் விண்ணுக்கு விருக்கு நிலையில் பிரியில் திலையில் திலையில்

பை கலைக்கார் இல்லில் பிருவல் நிலை இருக்கும் இல்லி கேடித்தில் தில்லி தல் கல்லை கல்லை பிரித்தில் நிலுக்கு நிலை நிலுக்கு பிருதல் கிறில் கல் இல்லில் கூடில் நிலையில் குண்டு முலுகின்கில் கிறில் கிறை நிலுக்கில் கிறுக்கு பிருதல் நிலுக்கு பிரிதில் பிருதுகிலில் கொண்டுக்குகில் கிறைக்குகில் கேடிலை திருதில் பிரி பிருதில் பிருதல் நிலை நிலுக்கு பிருதுகில் பிருதுகிலில் காரு பிருதில் கிறுக்குகில் கிறுக்கில் கிருதில் கிற பிரி பிருதில் கிறுக்கு பிருதல் நிலுக்கு பிருதுகிலில் காருக்கில் கிறுக்குக்குகில் கிறுக்கில் கிறைகளில் கிறுக்க பிருதில் கிறுக்கு பிருதல் பிருதில் பிருதுகிலில் காருகில் கிறுக்குகில் பிருதில் கேடில் கேடில் கிருதில் திருதில் பிருதில் கிறுக்குகில் பிருதில் பிருதில் பிருதில் பிருதில் கிறுக்குகில் கிருதில் கிருதில் கிருதில் கிருதில் கிரை நிலுக்குகில் கிருதில் கிருதில் கிருதில் கிறுக்கு பிருதில் பிருதில் கிருதில் கிருதில் கிருதில் கிரைக்கில் கிருதி கிருகில் கிருதில் கிருதில் கிருதில் கிறுக்கு பிருதில் பிருதில் கிருதில் கிருதில் கிருதில் கிருதில் கிருதில் கிரை

> ကြောင်းကို ကြောင်းကြောင်းကြောင်းကြောင့် ကြောင်းကြောင့် ကြောင်းကြောင့် ကြောင်းကြောင့် ကြောင်းကြောင့် ကြောင်းကြောင်းကြောင်းကြောင့် ကြောင်းကြောင့် ကြောင့် ကြောင့် ကြောင့် ကြောင့် ကြောင့် ကြောင့် ကြောင့် ကြောင့် ကြော

计微数分钟 医多分分娩 经公司公司公司

2 March March & March 1997