

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRI
(Other instruction
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

FEB 25 10 59 AM '88

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ WIW

2. NAME OF OPERATOR

Chevron U.S.A. Inc.

3. ADDRESS OF OPERATOR

P.O. Box 670, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FSL and 1980' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, AT, OR, ETC.)

5. LEASE DESIGNATION AND SERIAL NO.

LC-031740-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Eunice Monument S. Uni

8. FARM OR LEASE NAME

9. WELL NO.

410

10. FIELD AND POOL, OR WILDCAT

Eunice Monument G/SA

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 18, T21S, R36E

12. COUNTY OR PARISH 13. STATE

Lea

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

Well P&A'd 2-22-88

MIRU, NDWH, NU BOP, Set 4" CIBP at 3855', break circulation w/10# BW, circ. clean, spot 6sx C neat f/3855' to 3730', POOH to 3718', displace csg w/10# salt gel mud. Run 4.34" gauge ring to 3696', set 5 1/2" CIBP at 3575', run bailer and dump 35' (4 1/2sx H neat) cmt on top of CIBP f/3575' to 3540'. Perf w/4" gun, 4 JHPF, at 1675', 90° phased, GIH w/ cmt rtnr to 1631'. pmp 9bbbls 10# BW thru rtnr and establish circulation to surface thru 7 5/8" intermediate csg at 2 BPM, set rtnr at 1631', pmp 250sx Class C neat at 3 BPM w/500psi, displace w/3bbbls 10# BW, circ. 25sx to surf. spot 15 sx C neat on top of rtnr, 142' f/1631' to 1489'. POOH w/setting tool, ND BOP GIH to 218', spot 23 sx C neat f/218' to surface, break out WH, install dry hole marker. RD MO PU, cut anchors, clean location.

CHANGE NAME AND OWNERSHIP BACK TO CONOCO INC., MEYER A-1 #14.

* EMSU 410 permit to drill replacement well is pending the completion and changing back to former operator of this report.

18. I hereby certify that the foregoing is true and correct

SIGNED M. E. Abbin

TITLE Staff Drilling Engr.

DATE Feb. 24, 1988

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

SJS

RECEIVED

MAR 21 1988

NOBIS SERVICE