

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN THE
(Other instructions
reverse side)

CATEGORY
on re-

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Conoco Inc.	8. FARM OR LEASE NAME Meyer A-1
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240	9. WELL NO. 7
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FNL & 1980' FEH - Unit Letter G	10. FIELD AND POOL, OR WILDCAT Cumant Yates 7 RVR Queen
14. PERMIT NO. 30-025-04679	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 18-21S-36E
	12. COUNTY OR PARISH Dea
	13. STATE nm

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒
REPAIR WELL ☐	CHANGE PLANE ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- DMIRU.
2. Dump 2 sxs (20') of cement w/dump barrel at 3740'. RTH w/CIBP & 2 3/8" workstring. Set CIBP at 3000'. Spot 25 sxs cement on CIBP. Pull up to 2740' & circulate. Unble w/10 ppq-mud.
 3. Pull up to 1545' & spot 305' cement plug from 1545'-1240' (30 sxs) wait on cement 12 hrs. Tag top of cement, if cement below 1240', fill to 1240'. POOH.
 4. Pay 4 SSPF at 1200'. POOH.
 5. Establish injection rate thru perfs and circulate up annulus w/10 ppq-mud. If injection rate cannot be established, up 50' up hole until injection is accomplished. Pump 260 sxs class "C" cement w/18% salt to circulate 5 1/2" x 7 3/8" annulus & fill 5 1/2" csg to surface. POOH. If cement does not circulate up annulus pump 25 sxs cement down annulus.
 6. Install P&A marker. For further information contact James Hedrick at 397-5869

18. I hereby certify that the foregoing is true and correct

SIGNED DF FINNEY

TITLE Administrative Supervisor

DATE June 27, 1988

(Leave space for Federal or State office use)

APPROVED BY OTHER AGENCY RESOURCES

TITLE

DATE

COMMITTEES OF APPROVAL, IF ANY:

*See instructions on Reverse Side

It is a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM - Casblad (6) ARCE (2) Amro (2) Ch... 1.1 7.0