

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
HOBBS, NEW MEXICO 88240

SUBMIT IN TRIP DATE
(Other instructions
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS 88240

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR CONOCO INC.	8. FARM OR LEASE NAME Meyer B-17
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit I	10. FIELD AND POOL, OR WILDCAT Eumont Queen Gas
14. PERMIT NO. 30-025-04693	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 17-215-36E
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Convert to useable W.B.

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- ① MIRU on 7-30-86. Run scraper to 3750'.
- ② Set RBP @ 3730' and plkr @ 3400'. Break down Eumont perms w/353 bbls gelled 10 ppg brine. Reset RBP @ 3350' & plkr @ 3050'. Breakdown upper Eumont w/ 320 bbls gelled 10 ppg brine.
- ③ Set cmt ret @ 3497' & sqz w/ 150 sxs Class "C" w/ 2% CaCl₂. Set cmt ret @ 3120' & sqz w/ 150 sxs class "C" cmt. WOC.
- ④ DO ret @ 3120' & 20' of green cmt. DO hard cmt from 3140' - 3325'. Tested sqz for 15 min @ 500 psi; held OK. Drill out stringers 3325' - 3497'. DO cmt ret & cmt from 3497' to 3697' Circ. hole clean and test to 500 psi for 15 min. held OK. Drill out CIBP @ 3730'. Tag fill @ 3870' in open hole. Cleaned out to 3910'.
- ⑤ Washed cones & fish @ 3910'. Milled over fish to 3918' & cleaned out to 3922'. Set RBP @ 3757'. Loaded csg w/ 9 ppg brine & tested to 500 psi for 30 min. Rel RBP & POOH. Rig down on 8-12-86.
- ⑥ This well is scheduled to go into Chevron's Eunice Monument South Unit.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Administrative Supervisor

DATE

9-9-86

(This space for Federal or State office use)

APPROVED BY

TITLE

ACCEPTED FOR RECORD

CONDITIONS OF APPROVAL, IF ANY:

SEP 26 1986

*See Instructions on Reverse Side

Under State law, it is a crime for any person knowingly and willfully to make any statement or representation as to any matter within its jurisdiction.

BLM - Carlsbad (6) ARCO (2) AMOCO (2) Chevron (1) File
Z A Eumont 9/30/86 E

RECEIVED
SEP 29 1986
HOBBS OFFICE