

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CLEAN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. State Oil & Gas Lease No. B-1511
2. Name of Operator Atlantic Richfield Company		7. Unit Agreement Name
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240		8. Form or Lease Name State "F" DE
4. Location of Well UNIT LETTER E 2310 FEET FROM THE North LINE AND 330 FEET FROM THE West LINE, SECTION 19 TOWNSHIP 21S RANGE 36E NMPM.		9. Well No. 1
15. Elevation (Show whether DF, RT, CR, etc.) 3635' DF		10. Field and Pool, or Wildcat Eumont Yates 7R0
12. County Lea		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/> Eumont Yates 7R0 zone only CHANGE PLANS <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 3927'. Presently completed in perms 3872-76'. Propose to P&A Eumont oil zone & recomplete to the Eumont Queen Gas zone in the following manner:

1. Rig up, kill well, install BOP & POH w/completion assy.
2. RIH w/cmt retr, set retr @ 3800'.
3. Squeeze Eumont Oil perms 3872-76' w/100 sx LWL cmt followed by 100 sx Cl C cmt cont'g 6# sd/sk.

Recompletion to the Eumont Queen Gas reported separately on Form C-101.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Dist. Drlg. Supv. DATE 8/24/76

APPROVED BY _____ TITLE _____ DATE 8/26/76

CONDITIONS OF APPROVAL, IF ANY: